CONTRACTS BP-1, 2, 3, 4, 5 \$ 31,289,498
APPROVED CHANGES TO DATE: \$ 1,734,897 5.54%

REVISED CURRENT CONTRACT VALUE: \$ 33,024,395

CURRENT PENDING CHANGES: \$ 31,964 5.65%
PROJ. CONTRACT VALUE WITH APPROX./PENDING CHANGES: \$ 33,056,360

REMAINING PROJ. CONTINGENCY W/ ACCEPTED AND PENDING CO's \$ 132,701
CONTINGENCY AS A % OF TOTAL PROJECT VALUE 0.32%

EST. VALUE

					EST. VALUE					
COR#	REFERENCE DOCUMENT	DESCRIPTION	STATUS	RESP.	VALUE	PENDING REVIEW	APPROVED COST	DATE SUBMITTED	DATE OF APPROVAL	Notes
	CCD / RFI	TOTALS			\$1,826,453.03	\$31,964.42	\$1,734,897.38			
	OOD / IM I				ψ1,020,400.00	ψο 1,004.4 <u>2</u>	ψ1,104,001.00			
		Decreased elevator speed; Added roof drain								
1	BP-2 PR 01	connections; Relocated masonry walls & removed	FE		(52,292.72)		(52,292.72)	01/28/20	02/03/20	
		column wrap; Revised steel framing layout								
2	Field Condition	Over excavation for column footings	FE		22,554.00		22,554.00	01/28/20	02/03/20	
3	BP-2 PR 02	Revised footings, foundations, columns, & egress lighting	FE		7,230.74		7,230.74	01/28/20	02/03/20	
4	Contractor Credit	Tax Deduction	FE		(130,893.00)		(130,893.00)	01/28/20	02/03/20	
		Stained in lieu of integrally colored ballroom CIP			` ' '		` '			
5	VE Item	columns	FE		0.00		0.00	02/03/20	02/17/20	
6		DFH bond deduct	FE		(600.00)		(600.00)	02/04/20	02/17/20	
7	Field Condition	Duct bank excavation/shoring	FE		88,500.00		88,500.00	02/05/20	02/10/20	
8	BP-1 PR 01	Moved face of concrete infill 4"	FE		(110.00)		(110.00)	02/11/20	02/17/20	
9	BP-2 PR 03	Added trash enclosure foundation, slab, and CMU	FE		21,394.75		21,394.75	02/12/20	03/02/20	
		wall; Added beam sizes/reactions			Ť		•			
10	BP-2 PR 05	Install electrical data logger	FE		1,270.00		1,270.00	02/11/20	02/17/20	
11	BP-2 PR 07	Added below grade grounding system	FE		20,610.00		20,610.00	02/11/20	03/02/20	
		Added demo of existing window; Revised masonry								
12	BP-2 PR 04	wall types; Revised foundation wall; Revised joist	FE		(48,964.96)		(48,964.96)	02/12/20	02/17/20	
		layouts/loading/bearing condition and changed			(1,11 11,		(-,,			
		ganged joists to w-beams								
13	BP-1 Owner	Added telescopic seating section break; Added cable	FE		1.364.00		1,364.00	02/17/20	03/02/20	
	Request	notches in front steps; Deleted front rails			,		,			
	BP-2 PR 06	Modified steel elevations/connections/dimensions;							00/00/00	
14		Revised reveal at top of CIP columns	FE		0.00		0.00	02/19/20	03/02/20	
45	DD 4 DD 00	· ·			40.007.00		40.007.00	00/00/00	00/00/00	
15	BP-1 PR 02	Added power for telescopic seating	FE FE		18,237.20		18,237.20	03/30/20	03/30/20 03/30/20	
16 17		Added cladding at exterior of escalator	FE		35,882.63		35,882.63			
18	Field Condition	Enlarged freight elevator opening	FE FE		4,677.89 34,681.00		4,677.89 34,681.00	03/30/20	03/30/20 03/30/20	
	BP-2 PR 08	Over excavation for column footings	FE FE					03/30/20	03/30/20	
19 20		Structural updates	FE FE		44,734.41 (6,261.00)		44,734.41 (6.261.00)	03/30/20	03/30/20	
21	LAX Request	Aluminum door hardware credit Added fiber conduit for park cameras	FE		3.350.82		3,350.82	04/20/20	05/04/20	
22		North Hall footing soil corrections	FE FE		641.50					
	Field Condition	Moved North Hall temp road from Fowler to Strupp					641.50	04/20/20	05/04/20	
23	Field Condition	contract	FE		0.00		0.00	04/21/20	05/04/20	
24	Alternates	BP-3.1 Alternates 1 & 2	FE		107,809.00		107,809.00	04/22/20	05/04/20	
		Revised North Hall column layout; Added CMU					·			
25	BP-2 PR 09	pilaster; Added concrete wall waterproofing; Revised	FE		(8,975.95)		(8,975.95)	04/23/20	05/04/20	
		steel framing					,			
26	Contractor Cr114	Crediting CRM's remaining plumbing and HVAC	ГГ		(0.00E 40)		(0.005.40)	04/02/00	05/04/20	
26	Contractor Credit	demo allowances	FE		(2,285.40)		(2,285.40)	04/23/20	05/04/20	
27	PR 10	Revised structural steel, edge of deck, Elevator 2	FE		62 OFF 75		62 055 75	04/27/20	05/04/20	
21	PR TU	CMU shaft, & plumbing keynotes	rc		63,955.75		63,955.75	04/27/20	05/04/20	
		Revised foundation plan, steel beam sizes, & grand								
28	PR 11	stair stringer; Added soffit, folding partition, & Won	FE		44,470.94		44,470.94	04/28/20	06/01/20	
		Door details								
		Wieser temp. retaining wall shoring; Crediting								
29	Contractor Credit	remaining winter and unforeseen condition	FE		(64,030.49)		(64,030.49)	04/28/20	05/04/20	
-		allowances			(3 /333 12)		(- , ,			
00	F: 110 ::::				7		7.00.00	0.4/02/22	05/01/00	
30	Field Condition	Additional Room A171 demo for new electrical install	FE		7,921.98		7,921.98	04/28/20	05/04/20	

31	RFI 89	Plumbing changes/clarifications	FE	553.91	553.91	05/29/20	06/22/20	
32	VOID	1 1						
33 34	Field Condition Field Condition	North Hall over excavation	FE	10,249.00 (5.814.00)	10,249.00	05/15/20 05/20/20	06/01/20	
34	Field Colldition	Removed waterproofing at concrete escalator pit Added elevator access control and wall protection	FE	(5,614.00)	(5,814.00)	05/20/20	06/01/20	
35	PR 12	pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new coiling doors in concessions	FE	36,758.07	36,758.07	05/27/20	06/01/20	
36	Field Condition	Delete seats at columns	FE	(2,019.13)	(2,019.13)	06/04/20	06/22/20	
37	PR 12.1	Added elevator access control and wall protection pads; Revised North Hall/skywalk connection; Addec concessions back countertops; Added North Hall trench drain; Added new colling doors in concessions	FE	28,297.61	28,297.61	06/10/20	06/29/20	
38	VOID							
39	Field Condition	Over excavation for entrance hall	FE	383.00	383.00	06/11/20	06/22/20	
40	Scope Addition	Added fireproofing and special inspection scope.	FE	42,990.00	42,990.00	06/11/20	06/22/20	Budgeted Work
41	PR 13	Misc drawing changes	FE	3,033.36	3,033.36	06/26/20	07/13/20	
42	RFI 151	Deleted two freight elevator disconnects and replaced with one per Inspector request	FE	7,362.67	7,362.67	07/01/20	08/27/20	
43	Scope Reduction	Deleted two concession countertops	FE	(6,987.00)	(6,987.00)	07/02/20	07/13/20	
44	Scope Reduction	Allowance credit	FE	(5,000.00)	(5,000.00)	07/02/20	07/13/20	
45	PR 14	Added 4 concourse restrooms to project scope	FE	92,392.07	92,392.07	07/08/20	07/13/20	Budgeted Work
46	Owner Request	Additional arena railing painting	FE	10,965.00	10,965.00	07/21/20	08/03/20	
47	Field Condition	Framing and drywalling Concession 2 bulkhead/soffi	t FE	2,018.00	2,018.00	07/21/20	08/03/20	
48	Owner Request	Drywall skimming after wallpaper removal in locker rooms	FE	2,511.00	2,511.00	07/21/20	08/03/20	
49	Quality	Switching to silicone sealant	FE	2,956.80	2,956.80	07/21/20	08/17/20	
50	Improvement Field Condition	CMU patching in bathrooms due to plumbing changes: Allowance credit	FE	(34,242.93)	(34,242.93)	07/21/20	08/27/20	
51	PR 13.1	changes: Allowance credit Grazzini pricing for additional bathroom tile and aluminum base in Entrance Hall/East Connector	FE	3,058.00	3,058.00	07/21/20	08/27/20	
52	PR 15	Added Concession 9 to scope Added concession back countertops to scope	FE	51,745.42	51,745.42	07/21/20	08/27/20	
53	PR 16	Changed concession coiling doors to manual;	FE	157.33	157.33	07/21/20	08/03/20	
54	PR 17	Revised Entrance Hall evebrow framing: Removed Added plumbing vent piping and cleanouts per DSPS	FE	18,626.09	18,626.09	07/21/20	08/17/20	
55	Field Condition	comments: Added power circuits to fire doors Provided structural fill at Entrance Hall	FE	4,757.00	4,757.00	07/21/20	08/03/20	
56	Field Condition	Lowered concession fire sprinklers to match new	FE	1,182.00	1,182.00	07/21/20	08/03/20	
57	Owner Request	ceiling elevation Drywall skimming after tile removal in showers	FE	2,194.64	2,194.64	07/28/20	08/27/20	
58	RFI 189	Added sound batt insulation in additional Type B and		2,367.00	2,367.00	07/28/20	08/17/20	
59	VOID	F walls	-	2,007.00	2,007.00	325/20	55.11/20	
60	Scope Reduction	Credit for not installing BP-2 door frames in CMU	FE	(1,610.00)	(1,610.00)	07/29/20	08/17/20	
61	PR 18	Changed curtain wall headers and Stair FF, CC, GG	FE	73,595.90	73,595.90	07/29/20	08/17/20	
62	RFI 165	from CFMF to steel Added new Concession #3 coiling door	FE	5,442.15	5,442.15	07/29/20	08/27/20	
63	VOID							
64	Scope Reduction	Replaced room A227 FRP finish to paint	FE	(708.00)	(708.00)	08/03/20	08/17/20	
65	Field Condition	Added wall tile at urinals	FE	3,914.00	3,914.00	08/04/20	08/27/20	
66	VOID	Revised CFS trusses for added catwalk below					1	
67	RFI 188	Ballroom floor	FE	10,552.00	10,552.00	08/18/20	09/10/20	
68	Owner Request	Added drop ceiling and vinyl base in room A177	FE	692.00	692.00	09/18/20	09/29/20	

69	PR 19	Added furring walls/finishes around added curtain	FE	60,568.10	60,568.10	09/23/20	09/29/20	
70	Scope Reduction	wall beams; Added unit heater in Truck 3 entrance; Removed metal panel from Ballroom East parapet	FE	(2,148.10)	(2,148.10)	08/25/20	09/10/20	
71	RFI 176	Added trash chute room lighting	FE	2,420.07	2,420.07	08/25/20	09/10/20	
72	Field Condition	Added section ID sign frames to new arena railings	FE	2,378.20	2,378.20	08/28/20	09/10/20	
73	Scope Reduction	Removed room A171 slab pour from Fowler's scope	FE	(1,270.00)	(1,270.00)	08/28/20	09/10/20	
74	Field Condition	Curtain wall joint enlargement	FE	11,145.20	11,145.20	09/22/20	09/29/20	
75	RFI 194	Added additional spray foam insulation in Entrance Hall evebrow cavity	FE	11,970.00	11,970.00	09/02/20	09/21/20	
76	Contractor Credit	Irwin Seating allowance credit	FE	(10,000.00)	(10,000.00)	09/02/20	09/21/20	
77	Owner Request	Added separate light switches for concession stand soffit lighting	FE	1,680.00	1,680.00	09/08/20	09/21/20	
78	Owner Request	Changed North Hall floor finish to polished concrete	FE	65,274.85	65,274.85	09/15/20	09/21/20	
79	RFI 163	Added power to additional restroom fixtures	FE	12,919.07	12,919.07	09/14/20	09/21/20	
80	Owner Request	Added additional railing section sign frames	FE	3,927.00	3,927.00	09/16/20	09/21/20	
81	PR 15.1	Concession 9 countertop	FE	8,195.00	8,195.00	09/16/20	09/21/20	
82	RFI 257	Added ADA shower grab bars, benches, and door stops	FE	3,101.45	3,101.45	09/18/20	09/29/20	
83	PR 18.1	Ford Metro additional labor for added steel curtain wall header beams	FE	8,825.20	8,825.20	09/22/20	09/29/20	
84	PR 20	Added new arena exhaust fan and other mechanical controls: Added steel column reinforcing	FE	106,295.81	106,295.81	09/24/20	09/29/20	Budgeted Work
85	Field Condition	Modified location/type of trash chute door	FE	8,482.40	8,482.40	10/01/20	10/12/20	
86	Owner Request	Added eye hooks in North Hall	FE	1,192.52	1,192.52	10/01/20	10/12/20	
87	Owner Request	Added plywood backing for wall art	FE	886.60	886.60	10/01/20	10/12/20	
88	Scope Reduction	Removed acoustical ceiling tiles from North Hall	FE	(16,800.00)	(16,800.00)	10/01/20	10/12/20	
89	Scope Reduction	Removed temporary stairs from Wieser's scope	FE	(2,800.00)	(2,800.00)	10/01/20	10/12/20	
90	Owner Request	Added spray foam insulation on concrete deck below concession cooler. Removed Production Office wall from HJ Martin's	FE	1,597.20	1,597.20	10/01/20	10/12/20	
91	Scope Reduction	scope	FE	(1,055.00)	(1,055.00)	10/01/20	10/12/20	
92	Scope Addition	Added plywood to sloped roof	FE	8,241.40	8,241.40	11/03/20	11/10/20	
93	Field Condition	Modified existing roof drains to be above meeting level ceiling	FE	2,293.61	2,293.61	10/06/20	10/22/20	
94	Scope Addition	Replace Arena AV system DSP to accommodate new speakers	FE	6,440.00	6,440.00	10/08/20	10/22/20	
95 96	VOID VOID							
97	PR 20.1	Added tube steel curtain wall beams and column reinforcement	FE	23,885.46	23,885.46	10/14/20	11/19/20	
98	Owner Request	Enlarged AV carts to accommodate the larger projectors	FE	445.00	445.00	10/15/20	11/02/20	
99	Scope Addition	Added ADA assistive listening system to Arena	FE	3,200.00	3,200.00	11/17/20	11/30/20	
100	Owner Request	sound system Replace Lobby N100 ceiling	FE	2,208.70	2,208.70	10/20/20	11/09/20	
101	PR 21	Added concession hand sinks	FE	16,767.02	16,767.02	10/21/20	11/10/20	
102	RFI 248	Added additional connection reinforcement for steel sequence 6 & 15	FE	15,027.70	15,027.70	10/27/20	11/30/20	
103	VOID VOID							
104 105	VOID							
106	VOID							
107	VOID							
108	PR 22	Added Arena speaker power	FE	82,717.05	82,717.05	11/02/20	11/19/20	
109	Field Condition	Added wire mesh below radiant tubing in slabs on deck	FE	0.00	0.00	11/09/20	11/19/20	

		Repainted arena stair nosings after chipped by						
110	Field Condition	seating crew Added arena exhaust fan steel; Modified Ballroom	FE	(1,950.00)	(1,950.00)	11/09/20	11/19/20	
111	PR 23	curtain wall tube steel headers: Added plumbing for	FE	32,144.50	32,144.50	11/12/20	11/30/20	
112	Field Condition	Changed Sequence 5 structural steel to CFS	FE	53,494.00	53,494.00	11/17/20	11/24/20	
113	Owner Request	Added room signs and updated main entrance sign with new branding	FE	2,257.50	2,257.50	11/18/20	12/08/20	
114	Scope Addition	with new branding Changed portion of Entrance Hall wall from wood to drywall with reveals	FE	2,728.00	2,728.00	11/18/20	11/30/20	
115	Field Condition	Added 6" of concrete to elevator pit floor	FE	816.81	816.81	11/23/20	11/30/20	
116	VOID							
117	Scope Addition	Expansion joint assembly changes	FE	3,010.87	3,010.87	11/24/20	12/14/20	
118	Field Condition	Additional precast cutting at skyway opening; Cast electrical into precast panels	FE	5,560.00	5,560.00	11/24/20	12/16/20	
119	Field Condition	Replace drinking fountain damaged by Strupp	FE	0.00	0.00	11/30/20	12/08/20	
120	Field Condition	Additional tile at Concession 9	FE	1,534.00	1,534.00	12/03/20	12/16/20	
121	Contractor Credit	Block Iron allowance credit	FE	(2,500.00)	(2,500.00)	12/08/20	01/12/21	
122	RFI 347	Added fire alarm devices in North Hall to	FE	2,551.98	2,551.98	12/09/20	01/12/21	
123	RFI 351	accommodate the operable partition wall location Added dampers to existing ductwork in North Hall	FE	7,343.00	7,343.00	12/09/20	01/12/21	
124	RFI 255	Added water supply valves to accommodate	FE	17,480.64	17,480.64	12/10/20	01/12/21	
125	Owner Request	Owner's maintenance needs Added infill stud wall at Concession 4	FE	1,435.50	1,435.50	12/10/20	01/12/21	
126	RFI 321	Added L-soffit to enclose beam in North Hall	FE	4,086.50	4,086.50	12/10/20	01/12/21	
				· ·			-	
127 128	RFI 357 VOID	Omitted Electrical Room N421 ceiling	FE	(1,391.70)	(1,391.70)	12/10/20	01/12/21	
129	Field Condition	Installled solid ACT grid in lieu of clouds in existing	FE	(2,928.10)	(2,928.10)	12/22/20	01/12/21	
130	Field Condition	entrance Installed North Hall operable partition pocket support	FE	10,635.90	10,635.90	12/16/20	01/12/21	
131	Scope Reduction	steel Removed Concession 3 stainless cabinet from	FE	(18,935.00)	(18,935.00)	12/17/20	01/12/21	
132	Owner Request	Stafford Smith's scope Added dante audio card to the existing mixer	FE	1,400.00	1,400.00	12/11/20	01/12/21	
133	Field Condition	Added existing fireproofing patching in existing	FE	11,030.50	11,030.50	12/22/20	01/12/21	
	RFI 311	entrance Changed West operable partition upper pocket wall	FE	· ·				
134	-	from CFS studs to CMU Added steel support below box seating due to cracks		4,452.25	4,452.25	12/24/20	01/12/21	
135	Field Condition	in existing concrete	rc .	1,603.80	1,603.80	12/31/20	01/12/21	
136	Scope Addition	Added railings around Stair CC/GG Changed Sequence 5 structural steel to CFS; Added	FE	5,252.10	5,252.10	01/19/21	02/02/21	
137	PR 24	alvol system feed tanks: Added wayfinding signage	FE	72,823.21	72,823.21	12/24/20	01/12/21	Budgeted Work
138	Owner Request	Added rooftop patio shade structure	FE	73,672.00	73,672.00	12/28/20	01/28/21	Budgeted Work
139	Owner Request	Added wireless intercom system in arena	FE	16,665.00	16,665.00	12/28/20	03/02/21	
140	RFI 356	Converted water softener to a duplex system	FE	12,374.67	12,374.67	12/31/20	01/21/21	
141	Owner Request	Changed box office window design	FE	3,778.06	3,778.06	12/31/20	01/12/21	
142	Owner Request	Upgraded existing pneumatic mechanical controls	FE	20,970.00	20,970.00	01/05/21	01/12/21	
143	Field Condition	Omitted South section of operable partition soffit in North Hall	FE	(5,743.10)	(5,743.10)	01/04/21	01/12/21	
144	Field Condition	Added steel stud furring walls/columns in North	FE	9,366.50	9,366.50	01/05/21	01/28/21	
145	Contractor Credit	Corridor A101 Allowance credit for commissioning contract	FE	(29,500.00)	(29,500.00)	01/05/21	01/12/21	
146	Field Condition	Repaired stucco and cornice in North Corridor A101	FE	6,361.82	6,361.82	01/07/21	01/28/21	
147	Contractor Credit	Omitted escalator cladding where not exposed	FE	(1,627.95)	(1,627.95)	01/07/21	01/21/21	
148	Owner Request	Added more polished concrete floor and omitted	FE	7,478.68	7,478.68	01/07/21	01/21/21	
149	Owner Request	more epoxy floor in North Hall	-	9,216.64	1,410.00	01/07/21	0 1/20/2 1	Not coming out of
		Added two exterior security cameras	FF		40.004.00		04/00/04	project
150	Owner Request	Replaced existing doors	FE	48,901.60	48,901.60	01/11/21	01/20/21	

151	VOID									
152	Owner Request	Revised Box Office countertop to have two worker	FE		1,721.50		1,721.50	01/18/21	02/02/21	
153	Field Condition	stations instead of three Changed from four to three box seating coiling fire	FE		13,622.65		13,622.65	01/18/21	02/16/21	
154	City Request	doors Increased Hallberg commissioning umbrella	FE		4,000.00		4,000.00	01/26/21	03/02/21	
155	Field Condition	insurance limit to meet city requirements Changed operable partition soffit location in North	FE		12,397.33		12,397.33	01/29/21	03/02/21	
156	Field Condition	Hall Downsized meeting room entrance monitors	FE		(12,830.00)		(12,830.00)	02/02/21	02/16/21	
157	Owner Request	Added wall tile in Entrance Hall	FE		5,261.00		5,261.00	02/02/21	03/02/21	
158	Field Condition	Added Ballroom operable partition steel	FE		11,891.00		11,891.00	02/02/21	02/16/21	
159	Field Condition	Leveled outer existing lobby floor for tile installation	FE		1,463.50		1,463.50	02/03/21	06/02/21	
160	VOID	Economic datas existing looply need for the installation			1,400.00		1,400.00	02/00/21	00/02/21	
161	VOID									
162	Scope Addition	Added walls below escalator	FE		1,332.95		1,332.95	02/03/21	03/02/21	
163	Inspector Request	Added fire extinguishers per inspector	FE		762.94		762.94	02/03/21	02/16/21	
164	Scope Addition	Changed Ballroom Service Hall wall guards	PE	LAX	(2,185.85)	(2,185.85)		03/08/21		sent to city
165	Owner Request	Omitted walls at Stair EE ships ladder	FE		(2,506.90)		(2,506.90)	02/09/21	03/02/21	
166	Owner Request	Revised East concession stainless cabinets	FE		1,908.50		1,908.50	02/09/21	04/08/21	
167	Owner Request	Added outlet and data in Open Office	FE		1,150.75		1,150.75	02/09/21	03/02/21	
168	Scope Addition	Added parapet rigid insulation to Wieser's scope	FE		10,121.25		10,121.25	02/09/21	03/02/21	
169	Scope Reduction	Omitted section of ballroom floor expansion joint assembly	FE		(2,627.28)		(2,627.28)	02/11/21	03/02/21	
170	Owner Request	Added corner guards on arena and concourse level	FE		4,336.46		4,336.46	02/11/21	03/02/21	
171	PR 25	Added Zielke display case; Added circuits for box seating fire doors	FE		10,391.24		10,391.24	02/15/21	03/10/21	
172	Scope Addition	Added roof blocking to Wieser's scope	FE		4,797.80		4,797.80	02/15/21	03/24/21	
173	Scope Addition	Added spray foam wall insulation at mechanical roof	FE		1,963.50		1,963.50	02/16/21	03/10/21	
174	VOID	Added concrete notabling and waterproofing at								
175	Field Condition	Added concrete patching and waterproofing at orecast panel/foundation wall ioints Changed from sealed concrete to polished concrete	FE		2,014.75		2,014.75	02/18/21	03/10/21	
176	Owner Request	Changed from sealed concrete to polished concrete floor in break room	FE		3,528.00		3,528.00	02/19/21	03/02/21	
177	Owner Request	Added door hardware for arena level doors	FE		4,370.29		4,370.29	02/23/21	03/10/21	
178	Owner Request	Added outlets in Concession 8	FE		800.76		800.76	02/23/21	03/10/21	
179	Owner Request	Added window film to Exhibit Hall doors	FE		2,649.79		2,649.79	02/24/21	03/10/21	
180	Owner Request	Replaced outside air dampers for the four existing AHUs	FE		7,954.00		7,954.00	03/08/21	03/24/21	
181	Scope Addition	Added wall covering and chair rail to the rest of meeting rooms	FE		22,235.90		22,235.90	03/09/21	04/26/21	
182	Owner Request	Increased size of office desk tops	FE		2,079.06		2,079.06	03/11/21	04/08/21	
183	Field Condition	Added fireproofing patching where electrician	FE		0.00		0.00	03/12/21	03/24/21	
184	Owner Request	scraped off Changed Office N203 from a storeroom to an entry lockset	FE		365.89		365.89	03/15/21	03/24/21	
185	VOID	IOCKSEL								
186	Field Condition	Moved mechanical room wall to fit water heaters	FE		1,769.90		1,769.90	03/16/21	04/08/21	
187	Field Condition	Modified curtain wall segment miters to fit ballroom openings	FE		5,352.02		5,352.02	03/18/21	04/20/21	
188	Scope Reduction	Omitted steel columns for fire doors	FE		(5,312.00)		(5,312.00)	03/18/21	04/08/21	
189	Scope Addition	Added operable partition pocket door in Exhibit Hall	FE		2,975.70		2,975.70	03/19/21	04/08/21	
190	Owner Request	Moved existing office desks to office level	FE		770.00		770.00	03/19/21	04/08/21	
191	Owner Request	Added city fiber vault along Second St	FE		2,912.61		2,912.61	03/24/21	03/12/21	
192	Scope Addition	Added phase 2 final cleaning to scope	FE		14,400.00		14,400.00	03/29/21	03/13/21	Budgeted Work
193	Scope Addition	Added power and keyed switches for patio shade structure and lights	FE		1,594.83		1,594.83	03/31/21	04/26/21	

194	PR 26	Added Entrance Hall roof access door; Added exhaust fan and fire dampers to elevator mechanical room	FE		17,753.41		17,753.41	03/31/21	04/26/21	
195	VOID	100111								
196	VOID									
197	Scope Addition	Added Type Q light fixture at Ballroom meeting room entrance	FE		3,802.14		3,802.14	04/07/21	04/26/21	
198	Scope Addition	Added stud cavity infill around Ballroom slab edge	FE		9,081.77		9,081.77	04/08/21	04/26/21	
199	Scope Addition	Added Entrance Hall lighting control touchscreen	FE		8,122.44		8,122.44	04/15/21	04/26/21	
200	Owner Request	Added wall protection to Stair BB walls	FE		8,062.00		8,062.00	04/20/21	05/05/21	
201	Owner Request	Added two cylinders to door N108A	FE		772.30		772.30	04/26/21	05/10/21	
202	PR 29	Replaced 13 arena doors; Added wall/door at freight elevator	FE		31,306.41		31,306.41	04/26/21	05/10/21	
203	Scope Addition	Added concrete slab removal in East concourse	FE		5,038.00		5,038.00	04/26/21	05/19/21	
204	Field Condition	Added spray foam insulation along existing exterior wall	FE		7,093.80		7,093.80	04/30/21	05/19/21	
205	Owner Request	Added narrower conference table	FE		2,975.85		2,975.85	05/04/21	06/02/21	
206	Scope Addition	Added firestopping and trims to Stair DD expansion joints	FE		4,668.40		4,668.40	05/12/21	07/12/21	
207	Field Condition	Lowered fire sprinklers due to conflicts above ceiling			5,753.39		5,753.39	05/13/21	07/12/21	
208	Scope Addition	Added corner guards in meeting rooms	FE		984.12		984.12	05/24/21	06/21/21	
209	PR 27	Added exterior light fixture flashing; Added cabinet and countertop in box office area; Added power receptacle below escalator; Changed AV control locations in meeting rooms	FE		13,370.86		13,370.86	05/26/21	06/21/21	
210	Scope Addition	Added firestopping at the head of wall in Stair EE and Stair DD	FE		8,383.10		8,383.10	05/26/21	06/21/21	
211	Owner Request	Added water and power for coffee maker in concession stand; Added power receptacles at concession stand openings	FE		3,091.52		3,091.52	05/26/21	06/21/21	
212	Field Condition	Modified metal panels for West Ballroom to fit the segmenting of the building	FE		13,448.00		13,448.00	05/26/21	06/14/21	
213	VOID									
214	Field Condition	Eliminated stainless steel finish and reduced size of Concourse coiling concession doors	FE		(6,010.00)		(6,010.00)	05/26/21	06/14/21	
215	Scope Addition	Added lighting dimming capability in North Hall and meeting rooms; Added separate circuits for Ballroom floor boxes; Added cord reel for South Hall booth	FE		35,038.21		35,038.21	05/26/21	06/21/21	
216	Scope Addition	Added access door and access panel in Stair EE	FE		3,737.68		3,737.68	05/27/21	07/12/21	
217	Field Condition	Added window testing	FE		0.00		0.00	06/08/21	06/21/21	
218	Scope Addition	Added reception desk logo	PE	LAX	1,483.10	1,483.10		06/10/21	0.015 : : : :	sent to city
219	Field Condition	Added new metal panels above box seating	FE		7,728.69		7,728.69	06/10/21	06/21/21	
220	Field Condition	Added steel beams, decking, and new roofing above existing office entry	FE		9,480.90		9,480.90	06/10/21	07/12/21	
221	Field Condition	Changed CMU infill to CFS infill in concession stand	FE		(168.70)		(168.70)	06/10/21	06/21/21	
222	Scope Addition	Added CFS walls from existing roof parapet to underside of Ballroom deck and trusses		ISG	8,368.80			06/10/21		sent to ISG
223	Owner Request	Changed A244 opening to lock from Concourse side	FE		1,783.97		1,783.97	06/10/21	06/21/21	
224	VOID									
225	Field Condition	Added CMU infill at existing office façade	FE		6,732.28		6,732.28	06/10/21	06/21/21	
226	PR 26.1	Added Entrance Hall roof access door; Added exhaust ductwork through the CMU wall in elevator mechanical room	FE		4,095.98		4,095.98	06/10/21	07/12/21	
227	Scope Addition	Changed WAP locations due to site survey	FE		6,343.19		6,343.19	06/10/21	06/21/21	

Field Condition	Lowered Ballroom operable partition soffit		ISG	9,091.50			06/14/21		sent to ISG
Owner Request	Added power to East Concourse concession doors	PE	LAX	9,526.19	9,526.19		06/15/21		sent to city
Scope Reduction	Credited portion of ISG's survey contract amount	FE		(12,000.00)		(12,000.00)	06/17/21	07/12/21	
Contractor Credit				(12,750.00)		(12,750.00)	06/23/21	07/12/21	
Scope Addition	Added plywood catwalk below Ballroom floor; Added additional plywood on Ballroom benches	FE		15,666.88		15,666.88	06/23/21	07/12/21	
Field Condition	Added rebar doweling new concrete slab into existing slab		ISG	970.20			06/23/21		sent to ISG
Scope Addition	Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector		ISG	4,024.00			06/24/21		sent to ISG
Field Condition	Added larger trim for the North Ballroom metal panels	PE	LAX	0.00	0.00		06/29/21		sent to city
Contractor Credit	Used different receptacles in the North Hall floor boxes	PE	LAX	(3,600.00)	(3,600.00)		07/14/21		sent to city
PR 30.1	Added condensate pumps for two existing AHUs	PE	LAX	3,307.98	3,307.98		07/14/21		sent to city
PR 30.2	Added new tile stair nosings to replace the original ones	PE	LAX	28,308.00	28,308.00		07/14/21		sent to city
Scope Addition	Added ductwork/grilles/fire dampers to serve Trash Chute A252 and Hall A244		ISG	6,717.00			07/14/21		sent to ISG
Scope Reduction	Omitted exterior concrete pavement removal on Northwest side	PE	LAX	(1,245.00)	(1,245.00)		07/14/21		sent to city
Scope Reduction	Omitted metal panel above Truck Access A150 entrance	PE	LAX	(1,400.00)	(1,400.00)		07/14/21		sent to city
Scope Addition	Added carpet stair nosings in Stair CC/GG and edge trim on the meeting level		ISG	1,469.52			07/14/21		sent to ISG
Scope Reduction	Omitted sloped roof paint	PE	LAX	(2,230.00)	(2,230.00)		07/14/21		sent to city
Owner Request	propylene to ethylene	PE	LAX	0.00	0.00		07/20/21		sent to city
Field Condition	Added larger trim for the South Ballroom metal panels	PE	LAX	0.00	0.00		07/20/21		sent to city
	Owner Request Scope Reduction Contractor Credit Scope Addition Field Condition Field Condition Contractor Credit PR 30.1 PR 30.2 Scope Addition Scope Reduction Scope Reduction Scope Reduction Scope Reduction Owner Request	Owner Request Scope Reduction Credited portion of ISG's survey contract amount Contractor Credit Scope Addition Field Condition Scope Addition Added additional plywood on Ballroom benches Added rebar doweling new concrete slab into existing slab Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector Field Condition Contractor Credit PR 30.1 Added larger trim for the North Ballroom metal panels Used different receptacles in the North Hall floor boxes PR 30.1 Added condensate pumps for two existing AHUs PR 30.2 Added new tile stair nosings to replace the original ones Added ductwork/grilles/fire dampers to serve Trash Chute A252 and Hall A244 Scope Reduction Scope Reduction Scope Addition Scope Reduction Scope Reduction Scope Reduction Added carpet stair nosings in Stair CC/GG and edge trim on the meeting level Omitted stoped roof paint Added pot feeders/filters to the hot and cold water glycol systems; Changed hot water glycol from propylene to ethylene Field Condition Added larger trim for the South Ballroom metal	Owner Request Scope Reduction Credited portion of ISG's survey contract amount FE Contractor Credit Scope Addition Field Condition Scope Addition Added additional plywood catwalk below Ballroom floor; Added additional plywood on Ballroom benches Added rebar doweling new concrete slab into existing slab Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector Field Condition Field Condition Added larger trim for the North Ballroom metal panels Contractor Credit PR 30.1 Added condensate pumps for two existing AHUs PR 30.2 Added new tile stair nosings to replace the original ones Added ductwork/grilles/fire dampers to serve Trash Chute A252 and Hall A244 Scope Reduction Scope Reduction Scope Reduction Scope Addition Scope Reduction Scope Addition Scope Reduction Scope Addition Scope Reduction Omitted exterior concrete pavement removal on Northwest side Omitted metal panel above Truck Access A150 entrance Added carpet stair nosings in Stair CC/GG and edge trim on the meeting level Omitted sloped roof paint Added pot feeders/filters to the hot and cold water glycol systems; Changed hot water glycol from propylene to ethylene Field Condition Added larger trim for the North Ballroom metal	Owner Request Added power to East Concourse concession doors PE LAX Scope Reduction Credited portion of ISG's survey contract amount FE Contractor Credit Credited for using aluminum feeders in lieu of copper FE Scope Addition Added plywood catwalk below Ballroom floor; Added additional plywood on Ballroom benches Added rebar doweling new concrete slab into existing slab Scope Addition Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector Field Condition Added larger trim for the North Ballroom metal panels Contractor Credit Used different receptacles in the North Hall floor boxes PR 30.1 Added condensate pumps for two existing AHUs PE LAX PR 30.2 Added new tile stair nosings to replace the original ones Scope Addition Added ductwork/grilles/fire dampers to serve Trash Chute A252 and Hall A244 Omitted exterior concrete pavement removal on Northwest side Omitted exterior concrete pavement removal on Northwest side Omitted metal panel above Truck Access A150 PE LAX Added carpet stair nosings in Stair CC/GG and edge trim on the meeting level Owner Request Added larger trim for the South Ballroom metal PE LAX Eigld Condition PE LAX ILAX Added pot feeders/filters to the hot and cold water glycol systems; Changed hot water glycol from propylene to ethylene Added larger trim for the South Ballroom metal	Owner Request Added power to East Concourse concession doors PE LAX 9,526.19 Scope Reduction Credited portion of ISG's survey contract amount FE (12,000.00) Contractor Credit Credited for using aluminum feeders in lieu of copper FE (12,750.00) Scope Addition Added plywood catwalk below Ballroom floor; Added additional plywood on Ballroom benches Added rebar doweling new concrete slab into existing slab Scope Addition Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector ISG 4,024.00 Field Condition Contractor Credit Dowes Used different receptacles in the North Hall floor Dowes PE LAX 0.00 PR 30.1 Added condensate pumps for two existing AHUs PE LAX 3,307.98 PR 30.2 Added new tile stair nosings to replace the original ones Scope Addition Omitted exterior concrete pavement removal on Northwest side Omitted exterior concrete pavement removal on Northwest side Omitted exterior concrete pavement removal on Scope Reduction Scope Reduction Added carpet stair nosings in Stair CC/GG and edge trim on the meeting level Omitted store on PE LAX 0.00 Scope Reduction Omitted exterior concrete pavement condition on the meeting level Omitted sole of the deres/filters to the hot and cold water glycol systems; Changed hot water glycol from propylene to ethylene Added larger trim for the South Ballroom metal DE LAX 0.00 Eigld Condition PE LAX 0.00 Eigld Condition PE LAX 0.00 Eigld Condition PE LAX 0.00	Owner Request Added power to East Concourse concession doors Scope Reduction Credited portion of ISG's survey contract amount Contractor Credit Credited for using aluminum feeders in lieu of copper FE (12,000.00) Scope Addition Added plywood catwalk below Ballroom floor; Added additional plywood on Ballroom benches Field Condition Added rebar doweling new concrete slab into existing slab Scope Addition Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector Field Condition Added larger trim for the North Ballroom metal panels Description of Ballroom benches Field Condition Added larger trim for the North Hall floor boxes PR 30.1 Added condensate pumps for two existing AHUs PE LAX (3,600.00) (3,600.00) PR 30.1 Added condensate pumps for two existing AHUs PE LAX (3,000.00) (3,600.00) PR 30.2 Added new tile stair nosings to replace the original ones Scope Addition Added ductwork/grilles/fire dampers to serve Trash Chule A252 and Hall A244 Scope Reduction Omitted exterior concrete pavement removal on Northwest side Onto the exterior concrete pavement removal on Northwest side PE LAX (1,245.00) (1,245.00) Scope Addition Omitted exterior concrete pavement removal on the meeting level PE LAX (2,230.00) (2,230.00) Scope Reduction Omitted port feeders/filter to the hot and cold water glycol systems; Changed hot water glycol from propylene to ethylene Field Condition PE LAX (2,000.00) (2,230.00) FE LAX (2,000.00) (2,230.00) FE LAX (2,000.00) (2,230.00) FE LAX (2,000.00) (2,230.00)	Owner Request Added power to East Concourse concession doors PE LAX 9,526.19 9,526.19 Scope Reduction Credited portion of ISG's survey contract amount FE (12,000.00) (12,000.00) Contractor Credit Credited for using aluminum feeders in lieu of copper FE (12,750.00) (12,750.00) Scope Addition Added plywood catwalk below Ballroom floor; Added additional plywood on Ballroom benches Added rebar doweling new concrete slab into existing slab Scope Addition Added additional aluminum base in the Entrance Hall, Outer Lobby, and East Connector ISG 970.20 Field Condition Added larger trim for the North Ballroom metal panels Contractor Credit Used different receptacles in the North Hall floor boxes PR 30.1 Added condensate pumps for two existing AHUs PE LAX (3,600.00) (3,600.00) PR 30.2 Added new tile stair nosings to replace the original ones Scope Addition Chute A252 and Hall A244 Scope Reduction Northwest side Northwest side PE LAX (1,245.00) (1,245.00) Scope Reduction Omitted exterior concrete pavement removal on Northwest side PE LAX (1,400.00) (1,400.00) Scope Reduction Omitted exterior concrete pavement removal on Northwest side Isin nosings in Stair CC/GG and edge trim on the meeting level Scope Reduction Omitted exterior confering level Concept Scope Reduction Omitted exterior confering level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge trim on the meeting level Isin CC/GG and edge Isin CC/GG	Owner Request Added power to East Concourse concession doors PE LAX 9,526.19 9,526.19 06/15/21	Owner Request Added power to East Concourse concession doors PE LAX 9,526.19 9,526.19 06/15/21