CONTRACTS BP-1, 2, 3, 4 \$ 30,398,623 APPROVED CHANGES TO DATE: \$

REVISED CURRENT CONTRACT VALUE: \$ 1,114,853 31,513,476

CURRENT PENDING CHANGES: \$
PROJ. CONTRACT VALUE WITH APPROX./PENDING CHANGES: \$ 212,991 4.37% 31,726,467

REMAINING PROJ. CONTINGENCY W/ ACCEPTED AND PENDING CO's \$ 300,638 CONTINGENCY AS A % OF TOTAL PROJECT VALUE 0.72%

EST. VALUE

| | | | | EST. VALUE | | | | | |
|-------------------|--|--|-------------------------------|---|---|--|---|---|--|
| REFERENCE | | | RESP. | | PENDING | APPROVED | DATE | DATE OF | |
| DOCUMENT | DESCRIPTION | STATUS | PARTY | VALUE | REVIEW | COST | SUBMITTED | APPROVAL | Notes |
| CCD / RFI | TOTALS | | | \$1,327,844.23 | \$212,990.99 | \$1,114,853.24 | | | |
| | Decreed decretor and added as of ducin | | | | • | | | | |
| DD 0 DD 04 | | | | ¢50,000,70 | | 650 000 70 | 04/00/00 | 00/00/00 | |
| BP-2 PR 01 | | FE | | -\$52,292.72 | | -\$52,292.72 | 01/28/20 | 02/03/20 | |
| | column wrap; Revised steel framing layout | | | | | | | | |
| Field Condition | Over excavation for column footings | FE | | \$22,554.00 | | \$22,554.00 | 01/28/20 | 02/03/20 | |
| RP-2 PR 02 | Revised footings, foundations, columns, & egress | FF | | \$7 230 74 | | \$7 230 74 | 01/28/20 | 02/03/20 | |
| | lighting | | | | | | | | |
| Contractor Credit | | FE | | -\$130,893.00 | | -\$130,893.00 | 01/28/20 | 02/03/20 | |
| VE Item | | FE | | \$0.00 | | \$0.00 | 02/03/20 | 02/17/20 | |
| 0 1 2 2 2 2 | | FF | | | | • | | 00/47/00 | |
| | | | | | | | | | |
| | | | | | | | | | |
| DP-1 PR UI | | | | -\$110.00 | | -\$110.00 | 02/11/20 | 02/17/20 | |
| BP-2 PR 03 | | FE | | \$21,394.75 | | \$21,394.75 | 02/12/20 | 03/02/20 | |
| BP-2 PR 05 | | FF | | \$1 270 00 | | \$1 270 00 | 02/11/20 | 02/17/20 | |
| | | | | | | | | | |
| 5. 2 | | | | Ψ20,010.00 | | \$20,0.0.00 | 027.1720 | 00/02/20 | |
| | | | | -\$48,964.96 | | -\$48,964.96 | 02/12/20 | 02/17/20 | |
| RP_7 PR 04 | 31 . | FE | | | | | | | |
| | | | | | | | | | |
| | | | | ** *** | | ***** | | 00/00/00 | |
| | | FE | | \$1,364.00 | | \$1,364.00 | 02/17/20 | 03/02/20 | |
| • | • | | | | | | | | |
| BP-2 PR 06 | · · | FE | | \$0.00 | | \$0.00 | 02/19/20 | 03/02/20 | |
| | Revised reveal at top of CIP columns | | | | | | | | |
| BP-1 PR 02 | Added power for telescopic seating | FE | | \$18,237.20 | | \$18,237.20 | 03/30/20 | 03/30/20 | |
| Submittal Change | Added cladding at exterior of escalator | | | \$35,882.63 | | \$35,882.63 | 03/30/20 | 03/30/20 | |
| | | | | \$4,677.89 | | \$4,677.89 | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| Field Condition | | FE | | \$641.50 | | \$641.50 | 04/20/20 | 05/04/20 | |
| Field Condition | · | FE | | \$0.00 | | \$0.00 | 04/21/20 | 05/04/20 | |
| | | | | | | • | | | |
| Alternates | | FE | | \$107,809.00 | | \$107,809.00 | 04/22/20 | 05/04/20 | |
| DD 0 DD 00 | | | | 40.075.05 | | 00.075.05 | 0.4/00/00 | 05/04/00 | |
| | | FE | | -\$8,975.95 | ļ | -\$8,975.95 | 04/23/20 | 05/04/20 | |
| | | | | | | | | | |
| Contractor Credit | | FE | | -\$2,285.40 | | -\$2,285.40 | 04/23/20 | 05/04/20 | |
| | | | | | | | | | |
| PR 10 | | FE | | \$63,955.75 | | \$63,955.75 | 04/27/20 | 05/04/20 | |
| | | | | | | | | | |
| DD 11 | | FE | | \$44 470 04 | | \$44 470 04 | 04/28/20 | 06/01/20 | |
| | Door details | FE | | φ 44 ,470.94 | | Ф44,47 U.94 | 04/20/20 | 00/01/20 | |
| | | | | | | | | | |
| | Wieser temp, retaining wall shoring: Crediting | | 1 | | | | | | |
| Contractor Credit | Wieser temp. retaining wall shoring; Crediting remaining winter and unforeseen condition | FE | | -\$64,030.49 | | -\$64,030.49 | 04/28/20 | 05/04/20 | |
| | BP-2 PR 02 Contractor Credit Field Condition BP-2 PR 02 Contractor Credit VE Item Contractor Credit Field Condition BP-1 PR 01 BP-2 PR 03 BP-2 PR 05 BP-2 PR 07 BP-2 PR 04 BP-1 Owner Request BP-1 PR 02 Submittal Change Submittal Change Submittal Change Field Condition BP-2 PR 08 Contractor Credit LAX Request Field Condition Field Condition Alternates BP-2 PR 09 Contractor Credit PR 10 | DOCUMENT CCD / RFI Decreased elevator speed; Added roof drain connections; Relocated masonry walls & removed column wrap; Revised steel framing layout Field Condition BP-2 PR 02 Revised footings, foundations, columns, & egress lighting Contractor Credit Tax Deduction Stained in lieu of integrally colored ballroom CIP columns Contractor Credit DFH bond deduct Field Condition BP-1 PR 01 BP-2 PR 03 BP-2 PR 03 BP-2 PR 05 BP-2 PR 07 Added trash enclosure foundation, slab, and CMU wall; Added beam sizes/reactions BP-2 PR 07 Added delow grade grounding system Added delow grade grounding system Added demo of existing window; Revised masonry wall types; Revised foundation wall; Revised joist layouts/loading/bearing condition and changed ganged joists to w-beams BP-1 PR 02 Added telescopic seating section break; Added cable notches in front steps; Deleted front rails BP-2 PR 08 BP-1 PR 02 Added power for telescopic seating Submittal Change Field Condition BP-2 PR 08 Contractor Credit LAX Request Field Condition Alternates BP-3 I Alternates 1 & 2 Revised North Hall toolumn layout; Added CMU pilaster; Added concrete wall waterproofing; Revised structural steel, edge of deck, Elevator 2 CMU shaft, & plumbing keynotes Revised foundation plan, steel beam sizes, & grand | DOCUMENT CCD / RFI TOTALS | DOCUMENT CCD / RFI Decreased elevator speed; Added roof drain connections; Relocated masonry walls & removed column wrap; Revised steel framing layout Field Condition BP-2 PR 02 Revised footings, foundations, columns, & egress lighting Contractor Credit Tax Deduction VE Item Contractor Credit Diff bond deduct Field Condition BP-1 PR 01 BP-2 PR 03 BP-2 PR 05 BP-2 PR 05 BP-2 PR 07 Added beam sizes/reactions BP-2 PR 04 BP-2 PR 05 BP-1 Owner Request cable notches in front steps; Deleted front rails BP-1 Owner Request cable notches in front steps; Deleted front rails BP-1 PR 02 BB-1 PR 02 BB-1 PR 03 BB-1 PR 04 BB-2 PR 06 BB-1 PR 07 BB-2 PR 06 BB-1 Owner Request cable notches in front steps; Deleted front rails BP-1 PR 02 BUbmittal Change FE Submittal Change FE Submittal Change FE Added power for telescopic seating FE Submittal Change FE Added condition FE Added condition BP-2 PR 08 Contractor Credit LAX Request Field Condition Alternates BP-3 1 Alternates 8 BP-3 1 Alternates 1 & 2 Revised North Hall teoting planbing and HVAC demosilowand plans revised foundation plan, steel beam sizes, & grand FE Contractor Credit PR 10 Revised foundation plan, steel beam sizes, & grand | Decoument Description Status Party Value St.,327,844.23 | DOCUMENT COD / RFI TOTALS STATUS PARTY VALUE REVIEW COD / RFI TOTALS Status Stat | DOCUMENT DESCRIPTION STATUS PARTY VALUE REVIEW COST | DOCUMENT DESCRIPTION STATUS PARTY VALUE REVIEW COST SUBMITTED | DOCUMENT DESCRIPTION STATUS PARTY VALUE REVIEW COST SUBMITTED APPROVAL |

| 30 | Field Condition | Additional Room A171 demo for new electrical install | FE | \$7,921.98 | \$7,921.98 | 04/28/20 | 05/04/20 | |
|----------|---------------------------------|--|----------|----------------------------|----------------------------|----------------------|----------------------|---------------|
| 31 | RFI 89 | Plumbing changes/clarifications | FE | \$553.91 | \$553.91 | 05/29/20 | 06/22/20 | |
| 32 | VOID | | | 242.242.22 | ******* | 0.000 | 20101100 | |
| 33 | Field Condition Field Condition | North Hall over excavation Removed waterproofing at concrete escalator pi | FE FE | \$10,249.00 -\$5,814.00 | \$10,249.00 -\$5,814.00 | 05/15/20 05/20/20 | 06/01/20 06/01/20 | |
| 35 | PR 12 | Added elevator access control and wall protection pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new coiling doors in concessions | | \$36,758.07 | \$36,758.07 | 05/27/20 | 06/01/20 | |
| 36 | Field Condition | Delete seats at columns | FE | -\$2,019.13 | -\$2,019.13 | 06/04/20 | 06/22/20 | |
| 37 | PR 12.1 | Added elevator access control and wall protection pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new coiling doors in concessions | | \$28,297.61 | \$28,297.61 | 06/10/20 | 06/29/20 | |
| 38 | VOID | | | | | | | |
| 39 | Field Condition | Over excavation for entrance hall | FE | \$383.00 | \$383.00 | 06/11/20 | 06/22/20 | |
| 40 | Scope Addition | Added fireproofing and special inspection scope. | FE | \$42,990.00 | \$42,990.00 | 06/11/20 | 06/22/20 | Budgeted Work |
| 41 | PR 13 | Misc drawing changes | FE | \$3,033.36 | \$3,033.36 | 06/26/20 | 07/13/20 | |
| 42 | RFI 151 | Deleted two freight elevator disconnects and replaced with one per Inspector reques | FE | \$7,362.67 | \$7,362.67 | 07/01/20 | 08/27/20 | |
| 43 | Scope Reduction | Deleted two concession countertops | FE | -\$6,987.00 | -\$6,987.00 | 07/02/20 | 07/13/20 | |
| 44 | Scope Reduction | Allowance credit | FE | -\$5,000.00 | -\$5,000.00 | 07/02/20 | 07/13/20 | |
| 45 | PR 14 | Added 4 concourse restrooms to project scope | FE | \$92,392.07 | \$92,392.07 | 07/08/20 | 07/13/20 | Budgeted Worl |
| 46 | Owner Request | Additional arena railing painting | FE | \$10,965.00 | \$10,965.00 | 07/21/20 | 08/03/20 | |
| 47 | Field Condition | Framing and drywalling Concession 2 bulkhead/soffit Drywall skimming after wallpaper removal in locker | FE | \$2,018.00 | \$2,018.00 | 07/21/20 | 08/03/20 | |
| 48 | Owner Request | Drywall skimming after wallpaper removal in locker rooms | FE | \$2,511.00 | \$2,511.00 | 07/21/20 | 08/03/20 | |
| 49 | Quality Improvement | Switching to silicone sealant | FE | \$2,956.80 | \$2,956.80 | 07/21/20 | 08/17/20 | |
| 50 | Field Condition | CMU patching in bathrooms due to plumbing changes: Allowance credit Grazzini pricing for additional bathroom tile and | FE | -\$34,242.93 | -\$34,242.93 | 07/21/20 | 08/27/20 | |
| 51 | PR 13.1 | Grazzini pricing for additional bathroom tile and aluminum base in Entrance Hall/East Connector | FE | \$3,058.00 | \$3,058.00 | 07/21/20 | 08/27/20 | |
| 52 | PR 15 | Added Concession 9 to scope Added concession back countertops to scope | FE | \$51,745.42 | \$51,745.42 | 07/21/20 | 08/27/20 | |
| 53 | PR 16 | Changed concession coiling doors to manual; | FE | \$157.33 | \$157.33 | 07/21/20 | 08/03/20 | |
| 54 | PR 17 | Revised Entrance Hall evebrow framing: Removed Added plumbing vent piping and cleanouts per DSPS comments: Added power circuits to fire doors | FE | \$18,626.09 | \$18,626.09 | 07/21/20 | 08/17/20 | |
| 55 | Field Condition | Provided structural fill at Entrance Hall | FE | \$4,757.00 | \$4,757.00 | 07/21/20 | 08/03/20 | |
| 56 | Field Condition | Lowered concession fire sprinklers to match new ceiling elevation | FE | \$1,182.00 | \$1,182.00 | 07/21/20 | 08/03/20 | |
| 57 | Owner Request | Drywall skimming after tile removal in showers | FE | \$2,194.64 | \$2,194.64 | 07/28/20 | 08/27/20 | |
| 58 | RFI 189 | Added sound batt insulation in additional Type B and F walls | FE | \$2,367.00 | \$2,367.00 | 07/28/20 | 08/17/20 | |
| 59 | VOID | | | | | | | |
| 60 | Scope Reduction | Credit for not installing BP-2 door frames in CMU Changed curtain wall headers and Stair FF, CC, GG | FE | -\$1,610.00 | -\$1,610.00 | 07/29/20 | 08/17/20 | |
| 61 | PR 18 | from CFMF to steel | FE | \$73,595.90 | \$73,595.90 | 07/29/20 | 08/17/20 | |
| 62 | RFI 165 | Added new Concession #3 coiling door | FE | \$5,442.15 | \$5,442.15 | 07/29/20 | 08/27/20 | |
| 63 64 | VOID Scope Reduction | Replaced room A227 FRP finish to paint | FE | -\$708.00 | -\$708.00 | 08/03/20 | 08/17/20 | |
| 65 | Field Condition | Added wall tile at urinals | FE | · | \$3,914.00 | 08/04/20 | 08/27/20 | |
| CO | riela Condition | Added wall tile at utilials | rd | \$3,914.00 | \$3,914.00 | 00/04/20 | 00/2//20 | |

| 67 | RFI 188 | Revised CFS trusses for added catwalk below | FE | \$10,552.00 | \$10,552.00 | 08/18/20 | 09/10/20 | |
|------------|-------------------|--|----|--------------|--------------|----------|----------|---|
| 68 | Owner Request | Ballroom floor Added drop ceiling and vinyl base in room A177 | FE | \$692.00 | \$692.00 | 09/18/20 | 09/29/20 | |
| | | Added furring walls/finishes around added curtain | FE | | | | | |
| 69 | PR 19 | wall beams: Added unit heater in Truck 3 entrance: | | \$60,568.10 | \$60,568.10 | 09/23/20 | 09/29/20 | |
| 70 | Scope Reduction | Removed metal panel from Ballroom East parapet | FE | -\$2,148.10 | -\$2,148.10 | 08/25/20 | 09/10/20 | |
| 71 | RFI 176 | Added trash chute room lighting | FE | \$2,420.07 | \$2,420.07 | 08/25/20 | 09/10/20 | |
| 72 | Field Condition | Added section ID sign frames to new arena railings | FE | \$2,378.20 | \$2,378.20 | 08/28/20 | 09/10/20 | |
| 73 | Scope Reduction | Removed room A171 slab pour from Fowler's scope | FE | -\$1,270.00 | -\$1,270.00 | 08/28/20 | 09/10/20 | |
| 74 | Field Condition | Curtain wall joint enlargement | FE | \$11,145.20 | \$11,145.20 | 09/22/20 | 09/29/20 | |
| 75 | RFI 194 | Added additional spray foam insulation in Entrance Hall evebrow cavity | FE | \$11,970.00 | \$11,970.00 | 09/02/20 | 09/21/20 | |
| 76 | Contractor Credit | Irwin Seating allowance deduct | FE | -\$10,000.00 | -\$10,000.00 | 09/02/20 | 09/21/20 | |
| 77 | Owner Request | Added separate light switches for concession stand | FE | \$1,680.00 | \$1,680.00 | 09/08/20 | 09/21/20 | |
| 78 | Owner Request | soffit lighting Changed North Hall floor finish to polished concrete | FE | \$65,274.85 | \$65,274.85 | 09/15/20 | 09/21/20 | |
| 79 | RFI 163 | Added power to additional restroom fixtures | FE | \$12,919.07 | \$12,919.07 | 09/14/20 | 09/21/20 | |
| 80 | Owner Request | Added additional railing section sign frames | FE | \$3,927.00 | \$3,927.00 | 09/16/20 | 09/21/20 | |
| 81 | PR 15.1 | Concession 9 countertop | FE | \$8,195.00 | \$8,195.00 | 09/16/20 | 09/21/20 | |
| 82 | RFI 257 | Added ADA shower grab bars, benches, and door | FE | \$3,101.45 | \$3,101.45 | 09/18/20 | 09/29/20 | |
| | PR 18.1 | stops Ford Metro additional labor for added steel curtain | FE | | | 09/22/20 | 09/29/20 | |
| 83 | | wall header beams Added new arena exhaust fan and other mechanica | FE | \$8,825.20 | \$8,825.20 | | | D 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 |
| 84 | PR 20 | controls: Added steel column reinforcinc | - | \$106,295.81 | \$106,295.81 | 09/24/20 | 09/29/20 | Budgeted Work |
| 85 | Field Condition | Modified location/type of trash chute door | FE | \$8,482.40 | \$8,482.40 | 10/01/20 | 10/12/20 | |
| 86 | Owner Request | Added eye hooks in North Hall | FE | \$1,192.52 | \$1,192.52 | 10/01/20 | 10/12/20 | |
| 87 | Owner Request | Added plywood backing for wall art | FE | \$886.60 | \$886.60 | 10/01/20 | 10/12/20 | |
| 88 | Scope Reduction | Removed acoustical ceiling tiles from North Hall | FE | -\$16,800.00 | -\$16,800.00 | 10/01/20 | 10/12/20 | |
| 89 | Scope Reduction | Removed temporary stairs from Wieser's scope | FE | -\$2,800.00 | -\$2,800.00 | 10/01/20 | 10/12/20 | |
| 90 | Owner Request | Added spray foam insulation on concrete deck below concession cooler Removed Production Office wall from HJ Martin's | FE | \$1,597.20 | \$1,597.20 | 10/01/20 | 10/12/20 | |
| 91 | Scope Reduction | Removed Production Office wall from HJ Martin's scope | FE | -\$1,055.00 | -\$1,055.00 | 10/01/20 | 10/12/20 | |
| 92 | Scope Addition | Added plywood to sloped roof | FE | \$8,241.40 | \$8,241.40 | 11/03/20 | 11/10/20 | |
| 93 | Field Condition | Modified existing roof drains to be above meeting level ceiling | FE | \$2,293.61 | \$2,293.61 | 10/06/20 | 10/22/20 | |
| 94 | Scope Addition | Replace Arena AV system DSP to accommodate new speakers | FE | \$6,440.00 | \$6,440.00 | 10/08/20 | 10/22/20 | |
| 95 | VOID | new speakers | | | | | | |
| 96 | VOID | Added tube steel curtain wall beams and column | | | | | | |
| 97 | PR 20.1 | reinforcement | FE | \$23,885.46 | \$23,885.46 | 10/14/20 | 11/19/20 | |
| 98 | Owner Request | Enlarged AV carts to accommodate the larger projector screens | FE | \$445.00 | \$445.00 | 10/15/20 | 11/02/20 | |
| 99 | Scope Addition | Added ADA assistive listening system to Arena sound system | FE | \$3,200.00 | \$3,200.00 | 11/17/20 | 11/30/20 | |
| 100 | Owner Request | Replace Lobby N100 ceiling | FE | \$2,208.70 | \$2,208.70 | 10/20/20 | 11/09/20 | |
| 101 | PR 21 | Added concession hand sinks | FE | \$16,767.02 | \$16,767.02 | 10/21/20 | 11/10/20 | |
| 102 | RFI 248 | Added additional connection reinforcement for steel | FE | \$15,027.70 | \$15,027.70 | 10/27/20 | 11/30/20 | |
| 103 | VOID | sequence 6 & 15 | | | | | | |
| 104 105 | VOID VOID | | | | | | | |
| 106 | VOID | | | | | | 1 | |
| 107 | VOID | | | | | | | |

| 108 | PR 22 | Added Arena speaker power | FE | | \$82,717.05 | | \$82,717.05 | 11/02/20 | 11/19/20 | | |
|-----|-------------------|---|----|-----|--------------|--------------|-------------|----------|----------|-----------------|--------------------|
| 109 | Field Condition | Added wire mesh below radiant tubing in slabs on deck | FE | | \$0.00 | | \$0.00 | 11/09/20 | 11/19/20 | | |
| 110 | Field Condition | Repainted arena stair nosings after chipped by | FE | | -\$1,950.00 | | -\$1,950.00 | 11/09/20 | 11/19/20 | | |
| 111 | PR 23 | seating crew Added arena exhaust fan steel; Modified Ballroom curtain wall tube steel headers; Added plumbing for | FE | | \$32,144.50 | | \$32,144.50 | 11/12/20 | 11/30/20 | | |
| 112 | Field Condition | Changed Sequence 5 structural steel to CFS | FE | | \$53,494.00 | | \$53,494.00 | 11/17/20 | 11/24/20 | | |
| 113 | Owner Request | Added room signs and updated main entrance sign with new branding | FE | | \$2,257.50 | | \$2,257.50 | 11/18/20 | 12/08/20 | | |
| 114 | Scope Addition | with new branding Changed portion of Entrance Hall wall from wood to drywall with reveals | FE | | \$2,728.00 | | \$2,728.00 | 11/18/20 | 11/30/20 | | |
| 115 | Field Condition | Added 6" of concrete to elevator pit floor | FE | | \$816.81 | | \$816.81 | 11/23/20 | 11/30/20 | | |
| 116 | Field Condition | Ground down portion of Ballroom concrete slab & added fireproofing below | | KA | \$6,548.41 | \$6,548.41 | | 11/24/20 | | sent to ISG | Should Fowler |
| 117 | Scope Addition | Expansion joint assembly changes | FE | | \$3,010.87 | | \$3,010.87 | 11/24/20 | 12/14/20 | | _ r owici |
| 118 | Field Condition | Additional precast cutting at skyway opening; Cast electrical into precast panels | FE | | \$5,560.00 | | \$5,560.00 | 11/24/20 | 12/16/20 | | |
| 119 | Field Condition | Replace drinking fountain damaged by Strupp | FE | | \$0.00 | | \$0.00 | 11/30/20 | 12/08/20 | | |
| 120 | Field Condition | Additional tile at Concession 9 | FE | | \$1,534.00 | | \$1,534.00 | 12/03/20 | 12/16/20 | | |
| 121 | Contractor Credit | Block Iron allowance credit | PE | LAX | -\$2,500.00 | -\$2,500.00 | | 12/08/20 | | send PE to city | |
| 122 | RFI 347 | Added fire alarm devices in North Hall to accommodate the operable partition wall location | PE | LAX | \$2,551.98 | \$2,551.98 | | 12/09/20 | | send PE to city | 1 |
| 123 | RFI 351 | Added dampers to existing ductwork in North Hall | | ISG | \$7,343.00 | \$7,343.00 | | 12/09/20 | | Sent to ISG | more info/brea |
| 124 | RFI 255 | Added water supply valves to accommodate Owner's maintenance needs | PE | LAX | \$17,480.64 | \$17,480.64 | | 12/10/20 | | send PE to city | |
| 125 | Owner Request | Added infill stud wall at Concession 4 | PE | LAX | \$1,435.50 | \$1,435.50 | | 12/10/20 | | send PE to city | |
| 126 | RFI 321 | Added L-soffit to enclose beam in North Hall | | ISG | \$4,086.50 | \$4,086.50 | | 12/10/20 | | Sent to ISG | Talk witl Sean. |
| 127 | RFI 357 | Omitted Electrical Room N421 ceiling | PE | LAX | -\$1,391.70 | -\$1,391.70 | | 12/10/20 | | send PE to city | |
| 128 | PR 12.2 | WHV pricing for added metal panel soffit at | | ISG | \$1,265.00 | \$1,265.00 | | 12/10/20 | | Sent to ISG | 11/3A3- 41. |
| 129 | Field Condition | Radisson connector Installed solid ACT grid in lieu of clouds in existing | PE | LAX | -\$2,928.10 | -\$2,928.10 | | 12/22/20 | | send PE to city | 1 |
| 130 | Field Condition | entrance Installed North Hall operable partition pocket support steel | PE | LAX | \$10,635.90 | \$10,635.90 | | 12/16/20 | | send PE to city | |
| 131 | Scope Reduction | Removed Concession 3 stainless cabinet from Stafford Smith's scope | PE | LAX | -\$18,935.00 | -\$18,935.00 | | 12/17/20 | | send PE to city | 1 |