## **29,615,322** 297,974 **29,913,296**

28,298 1.10% **29,941,594** CURRENT PENDING CHANGES: \$
PROJ. CONTRACT VALUE WITH APPROX./PENDING CHANGES: \$

LCC Expansion & Renovation COR Log

REMAINING PROJ. CONTINGENCY W/ ACCEPTED AND PENDING CO's \$	879.637
<b>CONTINGENCY AS A % OF TOTAL PROJECT VALUE</b>	2.11%

					CONTINGENCY AS A % OF TOTAL PROJECT VALUE					
COR #	REFERENCE DOCUMENT	DESCRIPTION	STATUS	RESP. PARTY	VALUE	PENDING REVIEW	APPROVED COST	DATE SUBMITTED	DATE OF APPROVAL	Notes
	CCD / RFI	TOTALS			\$326,271.55	\$28,297.61	\$297,973.94			
1	BP-2 PR 01	Decreased elevator speed; Added roof drain connections; Relocated masonry walls & removed column wrap; Revised steel framing layout	FE		-\$52,292.72		-\$52,292.72	01/28/20	02/03/20	
2	Field Condition	Over excavation for column footings	FE		\$22,554.00		\$22,554.00	01/28/20	02/03/20	
		Revised footings, foundations, columns, & egress								
3	BP-2 PR 02 Contractor Credit	lighting Tax Deduction	FE FE		\$7,230.74 -\$130,893.00		\$7,230.74 -\$130,893.00	01/28/20	02/03/20 02/03/20	
5	VE Item	Stained in lieu of integrally colored ballroom CIP columns	FE		\$0.00		\$0.00	02/03/20	02/17/20	
6	Contractor Credit		FE		-\$600.00		-\$600.00	02/04/20	02/17/20	
7	Field Condition		FE		\$88,500.00		\$88,500.00	02/05/20	02/10/20	
8	BP-1 PR 01	Moved face of concrete infill 4"	FE		-\$110.00		-\$110.00	02/11/20	02/17/20	
9	BP-2 PR 03	Added trash enclosure foundation, slab, and CMU wall; Added beam sizes/reactions	FE		\$21,394.75		\$21,394.75	02/12/20	03/02/20	
10	BP-2 PR 05	Install electrical data logger	FE		\$1,270.00		\$1,270.00	02/11/20	02/17/20	
11	BP-2 PR 07	Added below grade grounding system	FE		\$20,610.00		\$20,610.00	02/11/20	03/02/20	
12	BP-2 PR 04	Added demo of existing window; Revised masonry wall types; Revised foundation wall; Revised joist layouts/loading/bearing condition and changed ganged joists to w-beams	FE		-\$48,964.96		-\$48,964.96	02/12/20	02/17/20	
13	BP-1 Owner Request	Added telescopic seating section break; Added cable notches in front steps; Deleted front rails	FE		\$1,364.00		\$1,364.00	02/17/20	03/02/20	1
14	BP-2 PR 06	Modified steel elevations/connections/dimensions; Revised reveal at top of CIP columns	FE		\$0.00		\$0.00	02/19/20	03/02/20	
15	BP-1 PR 02	Added power for telescopic seating	FE		\$18,237.20		\$18,237.20	03/30/20	03/30/20	
16	Submittal Change	Added cladding at exterior of escalator	FE		\$35,882.63		\$35,882.63	03/30/20	03/30/20	
17	Submittal Change		FE		\$4,677.89		\$4,677.89	03/30/20	03/30/20	
18	Field Condition		FE		\$34,681.00		\$34,681.00	03/30/20	03/30/20	
19	BP-2 PR 08		FE		\$44,734.41		\$44,734.41	03/30/20	03/30/20	
20	Contractor Credit		FE	-	-\$6,261.00		-\$6,261.00	03/30/20	03/30/20	
21	LAX Request Field Condition	Added fiber conduit for park cameras North Hall footing soil corrections	FE FE		\$3,350.82 \$641.50		\$3,350.82 \$641.50	04/20/20 04/20/20	05/04/20 05/04/20	
22	Field Condition	Moved North Hall temp road from Fowler to Strupp	FE		\$041.50		\$041.50	04/20/20	05/04/20	
24	Alternates	contract BP-3.1 Alternates 1 & 2	FE		\$107,809.00		\$107,809.00	04/22/20	05/04/20	
25	BP-2 PR 09	Revised North Hall column layout; Added CMU pilaster; Added concrete wall waterproofing; Revised steel framing	FE		-\$8,975.95		-\$8,975.95	04/23/20	05/04/20	
26	Contractor Credit	Crediting CRM's remaining plumbing and HVAC demo allowances	FE		-\$2,285.40		-\$2,285.40	04/23/20	05/04/20	
27	PR 10	Revised structural steel, edge of deck, Elevator 2 CMU shaft, & plumbing keynotes	FE		\$63,955.75		\$63,955.75	04/27/20	05/04/20	
28	PR 11	Door details	FE		\$44,470.94		\$44,470.94	04/28/20	06/01/20	
29	Contractor Credit	Wieser temp. retaining wall shoring; Crediting remaining winter and unforeseen condition allowances	FE		-\$64,030.49		-\$64,030.49	04/28/20	05/04/20	
30	Field Condition	Additional Room A171 demo for new electrical install	FE		\$7,921.98		\$7,921.98	04/28/20	05/04/20	
31	RFI 89	Plumbing changes/clarifications	FE		\$553.91		\$553.91	05/29/20	06/22/20	
33	Field Condition	North Hall over excavation	FE		\$10,249.00		\$10,249.00	05/15/20	06/01/20	
34	Field Condition	Removed waterproofing at concrete escalator pit Added elevator access control and wall protection	FE		-\$5,814.00		-\$5,814.00	05/20/20	06/01/20	
35	Partial PR 12	pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new coiling doors in concessions	FE		\$36,758.07		\$36,758.07	05/27/20	06/01/20	
36	Field Condition	Delete seats at columns	FE		-\$2,019.13		-\$2,019.13	06/04/20	06/22/20	
37	Partial PR 12	Added elevator access control and wall protection pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new colling doors in concessions	PE	LAX	\$28,297.61	\$28,297.61		06/10/20		
38	Owner Request	Add radiant tube heater at Truck 3	КА							
39	Field Condition	Over excavation for entrance hall	FE		\$383.00		\$383.00	06/11/20	06/22/20	
40	Added Scope	Added fireproofing and special inspection scope.	FE		\$42,990.00		\$42,990.00	06/11/20	06/22/20	Budgeted Item