Door details

allowances

Contractor Credit

Wieser temp. retaining wall shoring; Crediting remaining winter and unforeseen condition

FE

CONTRACTS BP-1, 2, 3, 4, 5 \$ 31,289,498

APPROVED CHANGES TO DATE: \$ 1,479,361

REVISED CURRENT CONTRACT VALUE: \$ 32,768,859

CURRENT PENDING CHANGES: \$ 112,038 5.09%

PROJ. CONTRACT VALUE WITH APPROX./PENDING CHANGES: \$ 32,880,897

REMAINING PROJ. CONTINGENCY W/ ACCEPTED AND PENDING CO's \$ 308,163
CONTINGENCY AS A % OF TOTAL PROJECT VALUE 0.74%

			CONTINGENCY AS A % OF TOTAL PROJECT VALUE EST. VALUE							
	REFERENCE			RESP.		PENDING	APPROVED	DATE	02/03/20 02/03/20 02/03/20 02/03/20 02/17/20 02/17/20 02/10/20	
COR#	DOCUMENT	DESCRIPTION	STATUS	PARTY	VALUE	REVIEW	COST	SUBMITTED		Notes
	CCD / RFI	TOTALS			\$1,591,398.88	\$112,038.11				
					+ 1,0001,000000	* * * * * * * * * * * * * * * * * * *	, 1, 11 0, 000 11 1			
	DD 0 DD 04	Decreased elevator speed; Added roof drain			050 000 70		050 000 70	04/00/00	00/00/00	
1	BP-2 PR 01	connections; Relocated masonry walls & removed	FE		-\$52,292.72		-\$52,292.72	01/28/20	02/03/20	
		column wrap; Revised steel framing layout								
2	Field Condition	Over excavation for column footings	FE		\$22,554.00		\$22,554.00	01/28/20	02/03/20	
3	BP-2 PR 02	Revised footings, foundations, columns, & egress	FE		\$7,230,74		\$7,230.74	01/28/20	02/03/20	
		lighting			, ,					
4	Contractor Credit	Tax Deduction	FE		-\$130,893.00		-\$130,893.00	01/28/20	02/03/20	
5	VE Item	Stained in lieu of integrally colored ballroom CIP	FE		\$0.00		\$0.00	02/03/20	02/17/20	
		columns					•		00/47/00	
6	Contractor Credit	DFH bond deduct	FE		-\$600.00		-\$600.00	02/04/20		
7	Field Condition	Duct bank excavation/shoring	FE		\$88,500.00		\$88,500.00	02/05/20	02/10/20	
8	BP-1 PR 01	Moved face of concrete infill 4"	FE		-\$110.00		-\$110.00	02/11/20	02/17/20	
9	BP-2 PR 03	Added trash enclosure foundation, slab, and CMU wall; Added beam sizes/reactions	FE		\$21,394.75		\$21,394.75	02/12/20	03/02/20	
10	BP-2 PR 05	Install electrical data logger	FE		\$1,270.00		\$1,270.00	02/11/20	02/17/20	
11	BP-2 PR 07	Added below grade grounding system	FE		\$20,610.00		\$20,610.00	02/11/20	03/02/20	
		Added demo of existing window; Revised masonry					7=0,010100		00.00.00	
		wall types; Revised foundation wall; Revised joist			***		***			
12	BP-2 PR 04	layouts/loading/bearing condition and changed	FE		-\$48,964.96		-\$48,964.96	02/12/20	02/17/20	
		ganged joists to w-beams								
13	BP-1 Owner	Added telescopic seating section break; Added	FE		\$1,364.00		\$1,364.00	02/17/20	03/02/20	
13	Request	cable notches in front steps; Deleted front rails	ГС		\$1,304.00		\$1,304.00	02/11/20	03/02/20	
		Modified steel elevations/connections/dimensions:								
14	BP-2 PR 06	Revised reveal at top of CIP columns	FE		\$0.00		\$0.00	02/19/20	03/02/20	
		· ·								
15	BP-1 PR 02	Added power for telescopic seating	FE		\$18,237.20		\$18,237.20	03/30/20	03/30/20	
16		Added cladding at exterior of escalator	FE		\$35,882.63		\$35,882.63	03/30/20	03/30/20	
17 18		Enlarged freight elevator opening	FE FE		\$4,677.89		\$4,677.89	03/30/20	03/30/20	
19	Field Condition BP-2 PR 08	Over excavation for column footings Structural updates	FE		\$34,681.00 \$44,734.41		\$34,681.00 \$44,734.41	03/30/20 03/30/20	03/30/20 03/30/20	
20		Aluminum door hardware credit	FE		-\$6,261.00		-\$6,261.00	03/30/20	03/30/20	
21	LAX Request	Added fiber conduit for park cameras	FE		\$3.350.82		\$3.350.82	04/20/20	05/04/20	
22	Field Condition	North Hall footing soil corrections	FE		\$641.50		\$641.50	04/20/20	05/04/20	
		Moved North Hall temp road from Fowler to Strupp								
23	Field Condition	contract	FE		\$0.00		\$0.00	04/21/20	05/04/20	
24	Alternates	BP-3.1 Alternates 1 & 2	FE		\$107,809.00		\$107,809.00	04/22/20	05/04/20	
		Revised North Hall column layout; Added CMU			7.17,111.00		, ,			
25	BP-2 PR 09	pilaster; Added concrete wall waterproofing;	FE		-\$8,975.95		-\$8,975.95	04/23/20	05/04/20	
		Revised steel framing								
26	Contractor Cradit	Crediting CRM's remaining plumbing and HVAC	FE		¢2 205 40		¢2 20E 40	04/23/20	05/04/20	
26	Contractor Credit	demo allowances	FE		-\$2,285.40		-\$2,285.40	04/23/20	05/04/20	
27	PR 10	Revised structural steel, edge of deck, Elevator 2	FE		\$63,955.75		\$63,955.75	04/27/20	05/04/20	
21	FRIU	CMU shaft, & plumbing keynotes	L		φυσ,900.75		დ სა,უსა.75	04/2//20	03/04/20	
		Revised foundation plan, steel beam sizes, & grand								
28	PR 11	stair stringer; Added soffit, folding partition, & Won	FE		\$44,470.94		\$44,470.94	04/28/20	06/01/20	

-\$64,030.49

-\$64,030.49

04/28/20

05/04/20

30	Field Condition	Additional Room A171 demo for new electrical install	FE	\$7,921.98	\$7,921.98	04/28/20	05/04/20	
31	RFI 89	Plumbing changes/clarifications	FE	\$553.91	\$553.91	05/29/20	06/22/20	
32	VOID			242.242.2	212.212.22	0.000	00/04/00	
33	Field Condition Field Condition	North Hall over excavation Removed waterproofing at concrete escalator pi	FE FE	\$10,249.00 -\$5,814.00	\$10,249.00 -\$5,814.00	05/15/20 05/20/20	06/01/20 06/01/20	
35	PR 12	Added elevator access control and wall protection pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new coiling doors in concessions		\$36,758.07	\$36,758.07	05/27/20	06/01/20	
36	Field Condition	Delete seats at columns	FE	-\$2,019.13	-\$2,019.13	06/04/20	06/22/20	
37	PR 12.1	Added elevator access control and wall protection pads; Revised North Hall/skywalk connection; Added concessions back countertops; Added North Hall trench drain; Added new coiling doors in concessions		\$28,297.61	\$28,297.61	06/10/20	06/29/20	
38	VOID							
39	Field Condition	Over excavation for entrance hall	FE	\$383.00	\$383.00	06/11/20	06/22/20	
40	Scope Addition	Added fireproofing and special inspection scope.	FE	\$42,990.00	\$42,990.00	06/11/20	06/22/20	Budgeted Work
41	PR 13	Misc drawing changes	FE	\$3,033.36	\$3,033.36	06/26/20	07/13/20	
42	RFI 151	Deleted two freight elevator disconnects and replaced with one per Inspector reques	FE	\$7,362.67	\$7,362.67	07/01/20	08/27/20	
43	Scope Reduction	Deleted two concession countertops	FE	-\$6,987.00	-\$6,987.00	07/02/20	07/13/20	
44	Scope Reduction	Allowance credit	FE	-\$5,000.00	-\$5,000.00	07/02/20	07/13/20	
45	PR 14	Added 4 concourse restrooms to project scope	FE	\$92,392.07	\$92,392.07	07/08/20	07/13/20	Budgeted Wor
46	Owner Request	Additional arena railing painting	FE	\$10,965.00	\$10,965.00	07/21/20	08/03/20	
47	Field Condition	Framing and drywalling Concession 2 bulkhead/soffit	FE	\$2,018.00	\$2,018.00	07/21/20	08/03/20	
48	Owner Request	bulkhead/soffit Drywall skimming after wallpaper removal in locker rooms	FE	\$2,511.00	\$2,511.00	07/21/20	08/03/20	
49	Quality Improvement	Switching to silicone sealant	FE	\$2,956.80	\$2,956.80	07/21/20	08/17/20	
50	Field Condition	CMU patching in bathrooms due to plumbing changes: Allowance credit Grazzini pricing for additional bathroom tile and	FE	-\$34,242.93	-\$34,242.93	07/21/20	08/27/20	
51	PR 13.1	Grazzini pricing for additional bathroom tile and aluminum base in Entrance Hall/East Connector	FE	\$3,058.00	\$3,058.00	07/21/20	08/27/20	
52	PR 15	Added Concession 9 to scope Added concession back countertops to scope	FE	\$51,745.42	\$51,745.42	07/21/20	08/27/20	
53	PR 16	Changed concession coiling doors to manual;	FE	\$157.33	\$157.33	07/21/20	08/03/20	
54	PR 17	Revised Entrance Hall evebrow framing: Removed Added plumbing vent piping and cleanouts per DSPS comments: Added power circuits to fire doors	FE	\$18,626.09	\$18,626.09	07/21/20	08/17/20	
55	Field Condition	Provided structural fill at Entrance Hall	FE	\$4,757.00	\$4,757.00	07/21/20	08/03/20	
56	Field Condition	Lowered concession fire sprinklers to match new ceiling elevation	FE	\$1,182.00	\$1,182.00	07/21/20	08/03/20	
57	Owner Request	Drywall skimming after tile removal in showers	FE	\$2,194.64	\$2,194.64	07/28/20	08/27/20	
58	RFI 189	Added sound batt insulation in additional Type B and F walls	FE	\$2,367.00	\$2,367.00	07/28/20	08/17/20	
59	VOID							
60	Scope Reduction	Credit for not installing BP-2 door frames in CMU Changed curtain wall headers and Stair FF, CC, GG	FE	-\$1,610.00	-\$1,610.00	07/29/20	08/17/20	
61	PR 18	from CFMF to steel	FE	\$73,595.90	\$73,595.90	07/29/20	08/17/20	
62	RFI 165	Added new Concession #3 coiling door	FE	\$5,442.15	\$5,442.15	07/29/20	08/27/20	
63 64	VOID Scope Reduction	Replaced room A227 FRP finish to paint	FE	-\$708.00	-\$708.00	08/03/20	08/17/20	
65	Field Condition	Added wall tile at urinals	FE	·	\$3,914.00	08/04/20	08/27/20	
CO	VOID	Added Wall tile at utilials	rc	\$3,914.00	\$3,914.00	00/04/20	00/2//20	

67	RFI 188	Revised CFS trusses for added catwalk below Ballroom floor	FE	\$10,552.00	\$10,552.00	08/18/20	09/10/20	
68	Owner Request	Added drop ceiling and vinyl base in room A177	FE	\$692.00	\$692.00	09/18/20	09/29/20	
69	PR 19	Added furring walls/finishes around added curtain	FE	\$60,568.10	\$60,568.10	09/23/20	09/29/20	
70	Scope Reduction	wall beams; Added unit heater in Truck 3 entrance; Removed metal panel from Ballroom East parapet	FE	-\$2,148.10	-\$2,148.10	08/25/20	09/10/20	
71	RFI 176	Added trash chute room lighting	FE	\$2,420.07	\$2,420.07	08/25/20	09/10/20	
72	Field Condition	Added section ID sign frames to new arena railings	FE	\$2,378.20	\$2,378.20	08/28/20	09/10/20	
		ů ů						
73	Scope Reduction	Removed room A171 slab pour from Fowler's scope		-\$1,270.00	-\$1,270.00	08/28/20	09/10/20	
74	Field Condition	Curtain wall joint enlargement Added additional spray foam insulation in Entrance	FE	\$11,145.20	\$11,145.20	09/22/20	09/29/20	
75	RFI 194	Hall evebrow cavity	FE	\$11,970.00	\$11,970.00	09/02/20	09/21/20	
76	Contractor Credit	Irwin Seating allowance deduct	FE	-\$10,000.00	-\$10,000.00	09/02/20	09/21/20	
77	Owner Request	Added separate light switches for concession stand soffit lighting	FE	\$1,680.00	\$1,680.00	09/08/20	09/21/20	
78	Owner Request	Changed North Hall floor finish to polished concrete	FE	\$65,274.85	\$65,274.85	09/15/20	09/21/20	
79	RFI 163	Added power to additional restroom fixtures	FE	\$12,919.07	\$12,919.07	09/14/20	09/21/20	
80	Owner Request	Added additional railing section sign frames	FE	\$3,927.00	\$3,927.00	09/16/20	09/21/20	
81	PR 15.1	Concession 9 countertop	FE	\$8,195.00	\$8,195.00	09/16/20	09/21/20	
82	RFI 257	Added ADA shower grab bars, benches, and door	FE	\$3,101.45	\$3,101.45	09/18/20	09/29/20	
83	PR 18.1	Ford Metro additional labor for added steel curtain	FE	\$8,825.20	\$8,825.20	09/22/20	09/29/20	
84	PR 20	wall header beams Added new arena exhaust fan and other mechanica controls: Added steel column reinforcinc	FE	\$106,295.81	\$106,295.81	09/24/20	09/29/20	Budgeted Work
85	Field Condition	Modified location/type of trash chute door	FE	\$8,482.40	\$8,482.40	10/01/20	10/12/20	
86	Owner Request	Added eye hooks in North Hall	FE	\$1,192.52	\$1,192.52	10/01/20	10/12/20	
87	Owner Request	Added plywood backing for wall art	FE	\$886.60	\$886.60	10/01/20	10/12/20	
88	Scope Reduction	Removed acoustical ceiling tiles from North Hall	FE	-\$16,800.00	-\$16,800.00	10/01/20	10/12/20	
89	Scope Reduction	Removed temporary stairs from Wieser's scope	FE	-\$2,800.00	-\$2,800.00	10/01/20	10/12/20	
90	Owner Request	Added spray foam insulation on concrete deck	FE	\$1,597.20	\$1,597.20	10/01/20	10/12/20	
91	Scope Reduction	below concession cooler Removed Production Office wall from HJ Martin's scope	FE	-\$1,055.00	-\$1,055.00	10/01/20	10/12/20	
92	Scope Addition	Added plywood to sloped roof	FE	\$8,241.40	\$8,241.40	11/03/20	11/10/20	
93	Field Condition	Modified existing roof drains to be above meeting level ceiling	FE	\$2,293.61	\$2,293.61	10/06/20	10/22/20	
94	Scope Addition	Replace Arena AV system DSP to accommodate new speakers	FE	\$6,440.00	\$6,440.00	10/08/20	10/22/20	
95	VOID							
96 97	VOID	Added tube steel curtain wall beams and column	FE	\$22.00F.40	#33.00F.40	10/14/20	11/10/00	
	PR 20.1	reinforcement Enlarged AV carts to accommodate the larger		\$23,885.46	\$23,885.46	10/14/20	11/19/20	
98	Owner Request	projectors	FE	\$445.00	\$445.00	10/15/20	11/02/20	
99	Scope Addition	Added ADA assistive listening system to Arena sound system	FE	\$3,200.00	\$3,200.00	11/17/20	11/30/20	
100	Owner Request	Replace Lobby N100 ceiling	FE	\$2,208.70	\$2,208.70	10/20/20	11/09/20	
101	PR 21	Added concession hand sinks	FE	\$16,767.02	\$16,767.02	10/21/20	11/10/20	
102	RFI 248	Added additional connection reinforcement for steel sequence 6 & 15	FE	\$15,027.70	\$15,027.70	10/27/20	11/30/20	
103 104	VOID VOID							
105	VOID							
106 107	VOID VOID							
107	VOID	1					1	1

108	PR 22	Added Arena speaker power	FE	\$82,717.05	\$82,717.05	11/02/20	11/19/20	
109	Field Condition	Added wire mesh below radiant tubing in slabs on	FE	\$0.00	\$0.00	11/09/20	11/19/20	
110	Field Condition	deck Repainted arena stair nosings after chipped by	FE	-\$1,950.00	-\$1,950.00	11/09/20	11/19/20	
111	PR 23	seating crew Added arena exhaust fan steel; Modified Ballroom	FE	\$32,144.50	\$32,144.50	11/12/20	11/30/20	
112	Field Condition	curtain wall tube steel headers: Added plumbing for Changed Sequence 5 structural steel to CFS	FE	\$53,494.00	\$53,494.00	11/17/20	11/24/20	
113	Owner Request	Added room signs and updated main entrance sign	FE	\$2,257.50	\$2,257.50	11/18/20	12/08/20	
		with new branding Changed portion of Entrance Hall wall from wood to						
114	Scope Addition	drvwall with reveals	rc .	\$2,728.00	\$2,728.00	11/18/20	11/30/20	
115 116	Field Condition VOID	Added 6" of concrete to elevator pit floor	FE	\$816.81	\$816.81	11/23/20	11/30/20	
117	Scope Addition	Expansion joint assembly changes	FE	\$3,010.87	\$3,010.87	11/24/20	12/14/20	
118	Field Condition	Additional precast cutting at skyway opening; Cast	FE	\$5,560.00	\$5,560.00	11/24/20	12/16/20	
119	Field Condition	electrical into precast panels Replace drinking fountain damaged by Strupp	FE	\$0.00	\$0.00	11/30/20	12/08/20	
120	Field Condition	Additional tile at Concession 9	FE	\$1,534.00	\$1,534.00	12/03/20	12/16/20	
121			FE		. ,		01/12/21	
	Contractor Credit	Block Iron allowance credit Added fire alarm devices in North Hall to	FE	-\$2,500.00	-\$2,500.00	12/08/20		
122	RFI 347	accommodate the operable partition wall location	+	\$2,551.98	\$2,551.98	12/09/20	01/12/21	
123	RFI 351	Added dampers to existing ductwork in North Hall Added water supply valves to accommodate	FE	\$7,343.00	\$7,343.00	12/09/20	01/12/21	
124	RFI 255	Owner's maintenance needs	FE	\$17,480.64	\$17,480.64	12/10/20	01/12/21	
125	Owner Request	Added infill stud wall at Concession 4	FE	\$1,435.50	\$1,435.50	12/10/20	01/12/21	
126	RFI 321	Added L-soffit to enclose beam in North Hall	FE	\$4,086.50	\$4,086.50	12/10/20	01/12/21	
127	RFI 357	Omitted Electrical Room N421 ceiling	FE	-\$1,391.70	-\$1,391.70	12/10/20	01/12/21	
128 129	VOID Field Condition	Installled solid ACT grid in lieu of clouds in existing	FE	-\$2,928.10	-\$2,928.10	12/22/20	01/12/21	
		entrance Installed North Hall operable partition pocket suppo	-		. ,			
130	Field Condition	steel Removed Concession 3 stainless cabinet from	'-	\$10,635.90	\$10,635.90	12/16/20	01/12/21	
131	Scope Reduction	Stafford Smith's scope	FE	-\$18,935.00	-\$18,935.00	12/17/20	01/12/21	
132	Owner Request	Added dante audio card to the existing mixer Added existing fireproofing patching in existing	FE	\$1,400.00	\$1,400.00	12/22/20	01/12/21	
133	Field Condition	entrance Changed West operable partition upper pocket wall	FE	\$11,030.50	\$11,030.50	12/22/20	01/12/21	
134	RFI 311	from CFS studs to CMU Added steel support below box seating due to	FE	\$4,452.25	\$4,452.25	12/24/20	01/12/21	
135	Field Condition	cracks in existing concrete	FE	\$1,603.80	\$1,603.80	12/31/20	01/12/21	
136	Scope Addition	Added railings around Stair CC/GG	FE	\$5,252.10	\$5,252.10	01/19/21	02/02/21	
137	PR 24	Changed Sequence 5 structural steel to CFS; Added glycol system feed tanks: Added wayfinding	FE	\$72,823.21	\$72,823.21	12/24/20	01/12/21	Budgeted Work
138	Owner Request	Added rooftop patio shade structure	FE	\$73,672.00	\$73,672.00	12/28/20	01/28/21	Budgeted Work
139	Owner Request	Added wireless intercom system in arena	FE	\$16,665.00	\$16,665.00	12/28/20	03/02/21	
140	RFI 356	Converted water softener to a duplex system	FE	\$12,374.67	\$12,374.67	12/31/20	01/21/21	
141	Owner Request	Changed box office window design	FE	\$3,778.06	\$3,778.06	12/31/20	01/12/21	
142	Owner Request	Upgraded existing pneumatic mechanical controls	FE	\$20,970.00	\$20,970.00	01/05/21	01/12/21	
143	Field Condition	Omitted South section of operable partition soffit in	FE	-\$5,743.10	-\$5,743.10	01/04/21	01/12/21	
144	Field Condition	North Hall Added steel stud furring walls/columns in North	FE	\$9,366.50	\$9,366.50	01/05/21	01/28/21	
145	Contractor Credit	Corridor A101 Allowance credit for commissioning contract	FE	-\$29,500.00	-\$29,500.00	01/05/21	01/12/21	
146	Field Condition	Repaired stucco and cornice in North Corridor A101		\$6,361.82	\$6,361.82	01/07/21	01/28/21	
147	Contractor Credit		FE	-\$1,627.95	-\$1,627.95	01/07/21	01/28/21	
147	Contractor Credit	Omitted escalator cladding where not exposed	rc	-\$1,027.95	-\$1,627.95	01/07/21	01/21/21	

148	Owner Request	Added more polished concrete floor and omitted more epoxy floor in North Hall	FE		\$7,478.68		\$7,478.68	01/07/21	01/28/21	In Owner's sourt
149	Owner Request	Added two exterior security cameras		LCC	\$9,216.64	\$9,216.64		01/11/21		In Owner's court. Process as 2 CORs
150	Owner Request	Replaced existing doors	FE		\$48,901.60		\$48,901.60	01/11/21	01/20/21	
151	VOID	Revised Box Office countertop to have two worker								
152	Owner Request	stations instead of three Changed from four to three box seating coiling fire	FE		\$1,721.50		\$1,721.50	01/18/21	02/02/21	
153	Field Condition	doors Increased Hallberg commissioning umbrella	FE		\$13,622.65		\$13,622.65	01/18/21	02/16/21	
154	City Request	insurance limit to meet city requirements Changed operable partition soffit location in North	FE		\$4,000.00		\$4,000.00	01/26/21	03/02/21	
155	Field Condition	Changed operable partition soffit location in North	FE		\$12,397.33		\$12,397.33	01/29/21	03/02/21	
156	Field Condition	Downsized meeting room entrance monitors	FE		-\$12,830.00		-\$12,830.00	02/02/21	02/16/21	
157	Owner Request	Added wall tile in Entrance Hall	FE		\$5,261.00		\$5,261.00	02/02/21	03/02/21	
158	Field Condition	Added Ballroom operable partition steel	FE		\$11,891.00		\$11,891.00	02/02/21	02/16/21	
159	Field Condition	Leveled outer existing lobby floor for tile installation		KA	\$7,213.00	\$7,213.00		02/03/21		sent to ISG
160	VOID									
161	VOID Seens Addition	Added wells below appeletor	FE		£4 222 0E		£4 222 0E	02/02/21	03/02/21	
162	Scope Addition	Added walls below escalator			\$1,332.95		\$1,332.95	02/03/21		
163	Inspector Request	Added fire extinguishers per inspector	FE		\$762.94		\$762.94	02/03/21	02/16/21	
164	Scope Addition	Changed Ballroom Service Hall wall guards		ISG	-\$2,185.85	-\$2,185.85		03/08/21		sent to ISG
165	Owner Request	Omitted walls at Stair EE ships ladder	FE		-\$2,506.90		-\$2,506.90	02/09/21	03/02/21	
166	Owner Request	Revised East concession stainless cabinets	PE	LAX	\$1,908.50	\$1,908.50		02/09/21		send PE to city
167	Owner Request	Added outlet and data in Open Office	FE		\$1,150.75		\$1,150.75	02/09/21	03/02/21	
168	Scope Addition	Added parapet rigid insulation to Wieser's scope	FE		\$10,121.25		\$10,121.25	02/09/21	03/02/21	
169	Scope Reduction	Omitted section of ballroom floor expansion joint assembly	FE		-\$2,627.28		-\$2,627.28	02/11/21	03/02/21	
170	Owner Request	Added corner guards on arena and concourse level	FE		\$4,336.46		\$4,336.46	02/11/21	03/02/21	
171	PR 25	Added Zielke display case; Added circuits for box seating fire doors	FE		\$10,391.24		\$10,391.24	02/15/21	03/10/21	
172	Scope Addition	Added roof blocking to Wieser's scope	FE		\$4,797.80		\$4,797.80	02/15/21	03/24/21	
173	Scope Addition	Added spray foam wall insulation at mechanical roo	fFE		\$1,963.50		\$1,963.50	02/16/21	03/10/21	
174	VOID						-			
175	Field Condition	Added concrete patching and waterproofing at precast panel/foundation wall joints Changed from sealed concrete to polished concrete	FE		\$2,014.75		\$2,014.75	02/18/21	03/10/21	
176	Owner Request	Changed from sealed concrete to polished concrete floor in break room	FE		\$3,528.00		\$3,528.00	02/19/21	03/02/21	
177	Owner Request	Added door hardware for arena level doors	FE		\$4,370.29		\$4,370.29	02/23/21	03/10/21	
178	Owner Request	Added outlets in Concession 8	FE		\$800.76		\$800.76	02/23/21	03/10/21	
179	Owner Request	Added window film to Exhibit Hall doors	FE		\$2,649.79		\$2,649.79	02/24/21	03/10/21	
180	Owner Request	Replaced outside air dampers for the four existing	FE		\$7,954.00		\$7,954.00	03/08/21	03/24/21	
181	Scope Addition	AHUS Added wall covering and chair rail to the rest of		ISG	\$22,235.90	\$22,235.90		03/09/21	1	sent to ISG
182	Owner Request	meeting rooms Increased size of office desk tops	PE	LAX	\$2,079.06	\$2,079.06		03/11/21		send PE to city
183	Field Condition	Added fireproofing patching where electrician	FE		\$0.00	+=,0.0.00	\$0.00	03/12/21	03/24/21	zziiz z z to olty
184	Owner Request	scraped off Changed Office N203 from a storeroom to an entry	FE		\$365.89		\$365.89	03/15/21	03/24/21	
	· '	lockset Added inside corner, division, and end cap trims to	, L	100	· ·	¢4.554.00	φ303.09		03/24/21	cont t- 100
185	Scope Addition	meeting room entrance FRI	PE	ISG	\$4,554.39	\$4,554.39		03/15/21		sent to ISG
186	Field Condition	Moved mechanical room wall to fit water heaters	PE	LAX	\$1,769.90	\$1,769.90		03/16/21	1	send PE to city

combine with

Wieser to talk

Wieser to

187	Fleia Condition	Modified curtain wall segment miters to fit ballroom openings		ISG	\$5,352.02	\$5,352.02	03/18/21	ISG approved	get revised T&M cor on docusign
188	Scope Reduction	Omitted steel columns for fire doors	PE	LAX	-\$5,312.00	-\$5,312.00	03/18/21	send PE to city	
189	Scope Addition	Added operable partition pocket door in Exhibit Hall	PE	LAX	\$2,975.70	\$2,975.70	03/19/21	send PE to city	
190	Owner Request	Moved existing office desks to office level	PE	LAX	\$770.00	\$770.00	03/19/21	send PE to city	