


Scoping Study | Report Summary | 3 July 2015




Site Plan (Existing)






Option A






Option B






Option B.2





Option C





View from riverfront - existing





View from riverfront - proposed





View from riverfront – proposed w/stair





View from west - existing






View from west - proposed





View from west – proposed w/stair





View from north - existing





View from north - proposed





View from northeast - existing





View from northeast - proposed





Second Street view – existing





Second Street view - proposed





View from Pearl - existing





View from Pearl - proposed





Parking structure – existing





Parking structure – proposed





View from southeast – existing





View from southeast – long range plan





General Upgrades



ORDER OF MAGNITUDE CONSTRUCTION COST

General Up	ograde	es		\$ 29,716,000	
	No.	Item	Description	Total	Note
GU	1	East Façade	New general lobby	\$ 4,400,000	
GU	2	West Façade	New circulation, meeting rooms	\$ 10,800,000	
			New continuous balconcy	\$ 1,635,300	
GU	3	Service Level	New service corridor	\$ 540,000	
GU	4	Exterior doors	Replace	\$ 390,000	
GU	5	Sustainability	Solar/wind power, other upgrades	\$ 250,000	Sundolier or similar
GU	6	LEED	Certification or LEED-compatible		
GU	7	HVAC	New building automation system	\$ 560,000	
GU	8	Exterior signage	Large scale LED signage	\$ 1,120,000	
GU	9	Exterior	Medium scale LED signs at entries	\$ 420,000	
GU	10	AV	Upgrade video projection to 16:9	\$ 200,000	
GU	11	Roof	Replace	\$ 2,840,000	
GU	12	Exterior	Upgrade façade (more brick)		included elsewhere
GU	13	IT	Upgrade infrastructure (fiber)	\$ 280,000	
GU	14	Interior	Upgrade wall finishes	\$ 4,260,000	
GU	15	Furnishings	Provide new for added space	\$ 2,020,000	
GU	16	Radisson Center	Long-range land use strategy	\$ 12,800,000	excluded from total

North Building



ORDER OF MAGNITUDE CONSTRUCTION COST

North Build	ding			\$ 8,060,000
	No.	Item	Description	Total
NB	1.A	Operable partitions	Repair or replace	\$ 640,000
NB	1.B	Lighting	New LED	\$ 130,000
NB	1.C	Sound system	Replace	\$ 100,000
NB	1.D	Exhibit/show power	Upgrade	\$ 100,000
NB	1.E	Floor	New or new finish	\$ 260,000
NB	1.F	Escalators	Rehab or replace	\$ 500,000
NB	2.A	Upper level	New ballroom	\$ 6,300,000
NB	2.B	Food service	Permanent bar	\$ 30,000
North Build	\$ 7,700,000			
	No.	Item	Description	Total
PH	1	Flexible theater	Raise roof, telescoping seats, acoustic	\$ 6,500,000
PH	2	Entry	New lobby on 2nd St.	\$ 1,200,000

Arena Upgrades ORDER OF MAGNITUDE CONSTRUCTION COST



Arena Upg	rades			\$ 10,470,000
	No.	Item	Description	Total
AU	1.A	Telescoping seating	Replace	\$ 540,000
AU	1.B	Arena lighting	New LED system	\$ 580,000
AU	1.C	Sound sytem	Replace	\$ 1,060,000
AU	1.D	Scoreboard	New video system	\$ 1,550,000
AU	1.E	Fixed seating	Replace	\$ 700,000
AU	1.F	ADA seating	Bring to compliance	\$ 100,000
AU	1.G	Seating Bowl	Deep clean and reseal	\$ 50,000
AU	1.H	Seating Bowl	Add supplemental exhaust	\$ 100,000
AU	2.A	Restrooms	Increase capacity	\$ 840,000
AU	2.B	Concessions	Increase capacity, variety	\$ 800,000
AU	2.C	Guest services	New spaces	\$ 70,000
AU	2.D	Administration	Relocate	\$ 880,000
AU	2.E	Box office	Expand to 6 windows	\$ 60,000
AU	2.F	Administration	Space for CVB offices	\$ 1,000,000
AU	3.A	Back of House	Improve traffic flow	\$ 500,000
AU	3.B	II	Access to spots/fall protection	\$ 120,000
AU	3.C	II	Upgrade show power	\$ 200,000
AU	3.D	II	Review/upgrade power building-wide	\$ 500,000
AU	3.E	п	Security/ops space	\$ 200,000
AU	3.F	II	Upgrade dressing rooms	\$ 450,000
AU	3.G	II	New dock levelers	\$ 70,000
	3.H	" Scaning Study Sumr	Fire alarm system upgrade	\$ 100,000

South Building & Garage ORDER OF MAGNITUDE CONSTRUCTION COST



South Build	ding			\$ 2,530,000
	No.	Item	Description	Total
SB	1.A	Ballroom	Expand prefunction toward river	\$ 1,260,000
SB	1.B	Business Center	Create new space	\$ 70,000
SB	1.C	Room signage	New LCD room signage	\$ 50,000
SB	2.A	South Hall	New telescoping portable seating	\$ 450,000
SB	2.B	Floor boxes	Replace with new	\$ 200,000
Parking Structure				\$ 3,980,000
	No.	Item	Description	Total
PS	1.A	Parking Structure	Façade enhancements	\$ 1,250,000
PS	1.B	Parking Structure	Large-scale LED display	\$ 2,730,000

Project Summary



Project Summary	\$ 62,456,000	\$ 6,246,000	\$	6,872,000	\$ 75,600,000
	Construction	Contingency	Fe	es, Testing	Total
GU General Upgrades*	\$ 29,716,000	\$ 2,972,000	\$	3,269,000	\$ 35,960,000
NB North Building	\$ 8,060,000	\$ 806,000	\$	887,000	\$ 9,760,000
PH Flexible Performance Space	\$ 7,700,000	\$ 770,000	\$	847,000	\$ 9,320,000
AU Arena Upgrades	\$ 10,470,000	\$ 1,047,000	\$	1,152,000	\$ 12,670,000
SB South Building	\$ 2,530,000	\$ 253,000	\$	279,000	\$ 3,070,000
PS Parking Structure	\$ 3,980,000	\$ 398,000	\$	438,000	\$ 4,820,000

^{*}excludes long-range facility expansion at Radisson Center site

Next steps



- Public Meetings
- Narrow and Focus Projects
- Capital Budgeting Process