




La Crosse Fire Department Inspection Report



Fire Department Information

Inspection Number: 20250422413
Inspector Name: Zurawski, Isaac

Inspection Date: 04/21/2025

Facility Information

Occupant Name: Tequila's Mexican Restaurant

Inspection Information

Date Completed: 04/21/2025

Inspection Type: Re-Inspection

Table with 5 columns: Code, Description, Comments, Re-inspection Date, Repaired Date. Contains 5 rows of inspection findings related to multiplug adapters, interior finish, extension cords, and emergency lighting.

(5) Stair shaft and vestibule of smokeproof enclosures, for which the following also apply:
 (a) The stair shaft and vestibule shall be permitted to include a standby generator that is installed for the smokeproof enclosure mechanical ventilation equipment.
 (b) The standby generator shall be permitted to be used for the stair shaft and vestibule emergency lighting power supply.
 (6) New access-controlled egress doors in accordance with 14.5.3.2 [101:7.9.1.1]


4.4.3.1.1	In every occupied building or structure, means of egress from all parts of the building shall be maintained free and unobstructed.		03/30/2025
11.1.2	All electrical appliances, fixtures, equipment, or wiring shall be installed and maintained in accordance with NFPA 70, National Electrical Code.		03/30/2025
63.3.1.8.4	Securing Compressed Gas Containers, Cylinders, and Tanks. - Compressed gas containers, cylinders, and tanks in use or in storage shall be secured to prevent them from falling or being knocked over by corralling them and securing them to a cart, framework, or fixed object by use of a restraint, unless otherwise permitted by 63.3.1.8.4.1 and 63.3.1.8.4.2. [55:7.1.8.4]		03/30/2025
50.4.6.1	Upon activation of any fire-extinguishing system for a cooking operation, all sources of fuel and electric power that produce heat to all equipment requiring protection by that system shall automatically shut off. [96:10.4.1]	Employee stats that it is broken and the stove turns off so he has to move the switch back to the open position so he can keep cooking. Adan	03/29/2025
63.3.1.8.4	Securing Compressed Gas Containers, Cylinders, and Tanks. - Compressed gas containers, cylinders, and tanks in use or in storage shall be secured to prevent them from falling or being knocked over by corralling them and securing them to a cart, framework, or fixed object by use of a restraint, unless otherwise permitted by 63.3.1.8.4.1 and 63.3.1.8.4.2. [55:7.1.8.4]		
11.1.7.6	Extension cords shall not be used as a substitute for permanent wiring.		
12.4.1	The installation and maintenance of assemblies and devices used to protect openings in walls, floors, and ceilings against the spread of fire and smoke within, into, or out		

of buildings shall comply with Section 12.4 and NFPA 80, Standard for Fire Doors and Other Opening Protectives. [80:1.1]


Violation Documents





















Inspection Notes:

Inspection Documents

Questions? Contact the LCFD Division of Community Risk Management at Fireinspections@cityoflacrosse.org or 608-789-7271



La Crosse Fire Department Inspection Report

Fire Department Information

Inspection Number: 202506232047
Inspector Name: Zurawski, Isaac

Inspection Date: 12/04/2025

Facility Information

Occupant Name: Tequila's Mexican Restaurant

Inspection Information

Date Completed: 12/04/2025

Inspection Type: Semi-Annual

Table with 3 columns: Code, Description, Re-inspection Date. Contains 3 rows of violation details including codes like 11.1.10 and 63.3.1.8.4.

Violation Documents

Inspection Notes:

Inspection Documents

Signatures

Table with 4 columns: Type, First Name, Last Name, Signature Date. Includes a signature box with a handwritten signature.

Questions? Contact the LCFD Division of Community Risk Management at Fireinspections@cityoflacrosse.org or 608-789-7271



La Crosse Fire Department Inspection Report

Fire Department Information

Inspection Number: 202512233908
Inspector Name: Zurawski, Isaac

Inspection Date: 05/05/2026

Facility Information

Occupant Name: Tequila's Mexican Restaurant


Inspection Information

Date Completed: 05/05/2026

Inspection Type: Semi-Annual

Table with 4 columns: Code, Description, Violations/Comments, and Re-inspection Date. Contains 5 rows of inspection findings.


Violation Documents



Inspection Notes:

Inspection Documents

Signatures

Type	First Name	Last Name	Signature Date	Signatures
Inspector	Isaac	Zurawski	05/05/2026	

Questions? Contact the LCFD Division of Community Risk Management at Fireinspections@cityoflacrosse.org or 608-789-7271