### City of La Crosse Housing Rehabilitation Program HOUSING REHABILITATION APPLICANT SUMMARY

**Application Number:** 128218 **Date Completed:** May 14, 2019

A. APPLICANT

Household Size: 2 Members Age(s): 38; 15

B. PROPERTY

**Location:** 3007 26th St S **Type of Property:** Single Family

Fair Market Value: \$108,600 Age of House: 1948

#### C. INSPECTION REPORT FINDINGS AND RECOMMENDATIONS

The HQS Inspection determined that there are minor electrical issues that need to be addressed to satisfy both HQS and Code Compliance; and structural repairs for the main floor system and at the rear deck. Improvements beyond the aforementioned are homeowner options and include roof replacement, new overhead garage door and adding a range hood/exhaust fan.

#### D. REHABILITATION WORK TO BE COMPLETED

- 1. Replace Overhead Garage Door
- 2. Install new gutters with leaf guard
- 3. Remove existing roofing and replace with new
  - a. Remove masonry chimney no longer needed
- 4. Floor joist reinforcement
- 5. Electrical HQS and Code Compliance
- 6. New Range Hood and Exhaust

F	TOTAL	COST OF REE	HABILITATION WORK	\$ 22,082,00
1/4	IVIAL	CAMPI OF REL		10 44.U04.UU

1. Hard Costs: \$ 22,082 2. Soft Costs: \$ 0

F. TOTAL CITY LOAN AMOUNT \$ 22,082.00

G. THE DEBT FACTOR IS: .98

**H. OTHER COMMENTS**: The homeowner recently had a new furnace and weatherization work completed by Couleecap.

## **Property Photo Summary**

Photo Summary 128418 128218 : Waiting

### **Property Photos**

Uploaded: 5/6/2019 Kevin Conroy



Uploaded: 5/6/2019 Kevin Conroy



Property Photo Summary 5/6/2019

1

# **Property Photo Summary**

## Photo Summary 128418

Uploaded: 5/6/2019 Kevin Conroy



128218 : Waiting

2

Uploaded: 5/6/2019 Kevin Conroy



Property Photo Summary 5/6/2019

# **Property Photo Summary**

## Photo Summary 128418

Uploaded: 5/6/2019 Kevin Conroy



128218 : Waiting

3

Uploaded: 5/6/2019 Kevin Conroy



Property Photo Summary 5/6/2019